

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009626/AVCN2**Date:** 22/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00171122000	
Claimant Vehicle No :	SMQ9209M	Insured Vehicle No :	SMW6900M	
Date of Loss:	11/09/2021	Nature of Claim:	TP	Claim No: SNM21D205159/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9209M		Engine No:	27091031910472
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)		Chassis No:	WDC1569422J659471
Reg. Date:	10/12/2019 (Man. Year: 2019)		Odometer:	26545 km
Colour:	Black			
Engine Capacity:	1595 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,934.30	3,052.20	882.10	22.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	560.00	1,650.00	74.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,144.30	3,612.20	2,532.10	41.21
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	6,144.30	2,850.00	3,294.30	53.62

INSPECTION

Date of Assignment:	11/10/2021		
Date Inspected:	14/09/2021	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9209M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,258.00 FN	*1,258.00 FN
2	1		*REAR BUMPER GARNISH	Deformed	645.00 FN	*450.00 FN
3	1		*REAR BUMPER DIFFUSER	Deformed	987.00 FN	*895.00 FN
4	1		*REAR BUMPER TOP CHROME	Cut	274.00 FN	*274.00 FN
5	1		*REAR PARKING SENSOR	Damaged	195.00 FN	*195.00 FN
6	1		*REINFORCEMENT	Not Necessary	682.00 FN	*- FN
7	1		*EXHAUST INSULATOR	Torn	150.00 FN	*150.00 FN
8	2		*BUMPER LOWER BRACKET	Damaged	136.00 FN	*136.00 FN
9	10		*BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
					Sub Total (\$\$)	4,367.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	432.70
					Total Parts (\$\$)	3,934.30
						3,052.20

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSTALL AND TRANSFER PARKING SENSORS TO NEW BUMPER	New	150.00	60.00
2	TO SCAN AND RESET PARKING SENSOR FAULT CODES	New	180.00	0.00
3	TO RESTORE REAR END PANEL INCLUDE KNOCKING AND WELDING TO REPLACE,INSTALL AND ALIGN ABOVE ITEMS	New	780.00	200.00
4	TO SPRAY PAINT REAR BUMPER AND END PANEL	New	800.00	250.00
5	TO SUPPLY AND TUFF KOTE	New	150.00	0.00
6	TO CARRY OUT WIRE TESTING AND CHECKING	New	150.00	50.00
Gross Labour Cost (\$)			2,210.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >