

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/FWD21009632/KES3Q2

Date:

14/10/2021

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00005034-03
Claimant Vehicle No :	SJD9374Y	Insured Vehicle No :	SLC3368L
Date of Loss:	13/09/2021	Nature of Claim:	TP
			Claim No: 1202100004987

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD9374Y		
Make & Model:	HONDA CITY, 1.5 VTEC (A)	Engine No:	LDA23027524
Reg. Date:	09/04/2008 (Man. Year: 2008)	Chassis No:	JHMF36208S208262
Colour:	Metallic Silver	Odometer:	156484 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Roadstar 7 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Roadstar 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,720.00	1,096.00	624.00	36.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	860.00	420.00	32.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,000.00	1,956.00	1,044.00	34.80
Approved Total (Overridden) (S\$)		1,500.00		

Nett Amount (S\$)	3,000.00	1,500.00	1,500.00	50.00
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/09/2021		
Date Inspected:	14/09/2021	Inspected At:	Thian Choon Auto Blk176 Sin Ming Drive, #05-02 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	4.0 days		

Adjuster:	KENNETH KONG	Manager:	Asher Sng Rong Yi
------------------	--------------	-----------------	-------------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2021)
Parts:	143	HONDA CITY 1.5 VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD9374Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH HEAD LAMP	Cut	480.00 F	*480.00 FL
2	1		*FRT BUMPER	Mtg Cracked	450.00 F	*450.00 FL
3	1		*FRT RH FENDER	Repair	380.00 F	*- FL
4	1		*FRT RH SPORT RIM (LOCAL REPAIR)	Dented / Cut	120.00 FS	*120.00 FS
5	1		*RH WING MIRROR	Mtg Distorted / Loose	290.00 F	*290.00 FL
					Sub Total (\$)	1,720.00
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00
					Total Parts (\$)	1,720.00
						1,340.00
						244.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ALIGNMENT RH	New	50.00	50.00
2	PANEL BEATING FRT AFFECTED AREA	New	550.00	350.00
3	SPRAY PAINTING FRT AFFECTED AREA	New	680.00	460.00
Gross Labour Cost (\$\$)			1,280.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >