



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3224X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | REAR BUMPER | DENTED | 1,075.00 | 1,023.00 |
| 2 | REAR BUMPER TOW COVER @\$45.00 | MISSING | 90.00 | 70.00 |
| 10 | REAR BUMPER CLIPS @\$4.00 | NECESSARY | 40.00 | 30.00 |
| 4 | REAR BUMPER RIVET @\$5.00 | NECESSARY | 20.00 | 10.00 |
| 2 | REAR BUMPER REFLECTOR @\$115.00 | NOT NECESSARY | 230.00 | - |
| 1 | REAR REINFORCEMENT | NOT NECESSARY | 545.00 | - |
| 1 | REAR END PANEL (NPA) | NOT NECESSARY | - | - |
| | LESS 20% DISCOUNT | | -400.00 | -226.60 |
| | | | 1,600.00 | 906.40 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SETS REAR REVERSE SENSOR (SN) | SHORTED | 280.00 | 200.00 |
| | | | 280.00 | 200.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REPLACED REAR REVERSE SENSOR. | | 100.00 | 30.00 |
| | TO KNOCKING & PANEL BEATING. | | 600.00 | 200.00 |
| | TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS. | | 600.00 | 200.00 |
| | | | 1,300.00 | 430.00 |
| | GRAND TOTAL | | 3,180.00 | 1,536.40 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,250.00 |

Report Ref No. CS/SMR21009637/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.