

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009641/DEA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBB6013P	Insured Vehicle No :	SLK4467K
Date of Loss:	12/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004008

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6013P	Engine No:	4M42A73482
Make & Model:	mitsubishi FB70BB1SRDEA, 3.0 D (M)	Chassis No:	FB70BBA20048
Reg. Date:	31/07/2009 (Man. Year: 2009)	Odometer:	656109 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Condor 5 mm	Rear Left Side:	Condor 5/5 mm
Front Right Side:	Condor 5 mm	Rear Right Side:	Condor 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,390.40	726.66	16,663.74	95.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	890.00	4,030.00	81.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,310.40	1,616.66	20,693.74	92.75
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	22,310.40	1,300.00	21,010.40	94.17
+ GST 7.00/7.00% (S\$)	1,561.73	91.00	1,470.73	94.17
Nett Amount (S\$)	23,872.13	1,391.00	22,481.13	94.17
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,177.45		

INSPECTION

Date of Assignment:	14/09/2021	JWG International Pte Ltd (HQ)
Date Inspected:	15/09/2021 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 26 Apr 2022)	
Parts:	N/A	mitsubishi FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB6013P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE GATE RH	Repair	2,021.20 FL	*- FL
2	1		*SIDE GATE HINGE RH	1 PCS Bent /5 PCS Not Necessary	954.00 FL	*104.21 FL
3	1		*FLOOR PANEL	Not Necessary	15,000.00 FL	*- FL
4	1		*REAR WHEEL ARC GARNISH RH	Cut Deformed	398.00 FL	*398.00 FL
5	1		*REAR RIM RH	Distorted	600.00 FS	*350.00 FS
6	1		*REAR WHEEL BEARING RH	Not Necessary	231.00 FL	*- FL
7	1		*REAR WHEEL BEARING HUB RH	Not Necessary	394.00 FL	*- FL
8	1		*REAR OUTPUT SHAFT RH	Not Necessary	2,789.00 FL	*- FL
9	1		*TYRE	Not Necessary	400.00 FS	*- FS
10	1		*REAR WHEEL ARC GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,837.20	852.21
- List Item Discount on L Items 25.00/25.00% (\$)	5,446.80	125.55
Total Parts (\$)	17,390.40	726.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	200.00	30.00
4	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
			Gross Labour Cost (\$)	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >