



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 280A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HANDLE BAR	SERVICEABLE	185.00	-
1	SET HANDLE BAR END BALANCER	ABRADED	50.00	50.00
1	LH MIRROR ASSY	SCRAPED	55.00	55.00
1	REAR SWING ARM ASSY	NOT NECESSARY	950.00	-
1	LHS PILLION FOOT PEG BRACKET	ABRADED	70.00	70.00
1	REAR NUMBER PLATE HOLDER	BENT / DEFORMED	29.00	29.00
1	LHS FRONT COWLING	SCRAPED / MOUNT BRKT DISTORTED	90.00	90.00
1	LHS FRONT COWLING "YAMAHA" LOGO	NECESSARY	15.00	15.00
1	LHS FRONT COWLING "TRACER 900" STICKER	NECESSARY	25.00	25.00
	LESS 10% DISCOUNT		-146.90	-33.40
			1,322.10	300.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BOX (SN)	DENTED / ABRADED	950.00	680.00
1	SET REAR NUMBER PLATE CUM FRAME (SN)	BENT	25.00	25.00
1	GIVI ENGINE / SPRAY GUARD MOUNTING KIT (SN)	DENTED / ABRADED	580.00	450.00
2	PUIG TRAIL FOOTPEG - FRONT & REAR LHS (SN)	DENTED / ABRADED	360.00	250.00
1	SET HAND GUARD (SN)	ABRADED	180.00	180.00
1	SET FRONT WHEEL CRASH SLIDER (SN)	ABRADED	180.00	180.00
1	SET FRAME CRASH SLIDER (SN)	ABRADED	90.00	90.00
1	SET REAR SWING ARM BUSH (SN)	NOT NECESSARY	100.00	-
1	LHS LED FRONT FLASHER LIGHT (SN)	ABRADED	280.00	150.00
1	SET FOG LAMP (SN)	DENTED / GRAZED	500.00	300.00
1	REAR WHEEL HUGGER BRACKET (SN)	BENT	75.00	75.00
1	REAR WHEEL HUGGER GIVI (SN)	BENT / DEFORMED	120.00	120.00
			3,440.00	2,500.00
	<b><u>LABOUR</u></b>			
	TOWING.		80.00	70.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK REAR WHEEL ALIGNMENT.		120.00	80.00
	DIAGNOSTIC CHECK ALL ELECTRICAL SYSTEM FOR CONDITIONS.		1,000.00	40.00
	LABOUR FOR REMOVING DAMAGED PARTS AND INSTALL NEW PARTS.		500.00	400.00
			1,700.00	590.00
<b>GRAND TOTAL</b>			<b>6,462.10</b>	<b>3,390.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,700.00</b>

Report Ref No. CS3/ASM21003347/T1vce2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.