

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009652/BVF3N2**Date:** 05/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001624063
Claimant Vehicle No :	SLG7239D	Insured Vehicle No :	SMR897E
Date of Loss:	12/09/2021	Nature of Claim:	TP
		Claim No:	262566

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7239D	Engine No:	K20Z23501702
Make & Model:	HONDA CIVIC, 2.0 L (A)	Chassis No:	JHMFD26408S201694
Reg. Date:	02/07/2008 (Man. Year: 2008)	Odometer:	288398 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,419.04	8,936.02	9,483.02	51.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	1,820.00	3,060.00	62.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,299.04	10,756.02	12,543.02	53.83
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	23,299.04	6,400.00	16,899.04	72.53
+ GST 7.00/7.00% (S\$)	1,630.93	448.00	1,182.93	72.53
Nett Amount (S\$)	24,929.97	6,848.00	18,081.97	72.53

INSPECTION

Date of Assignment:	15/09/2021	
Date Inspected:	17/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2021)
Parts: 143	HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG7239D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET SIDE RUBBER	Necessary	60.00 FL	*48.00 FL
2	1		*BONNET INNER LOCK	Jammed	279.00 FL	*162.80 FL
3	1		*BONNET LOCK CABLE	Jammed	254.90 FL	*101.00 FL
4	1		*BONNER INSULATOR	Torn	458.90 FL	*187.60 FL
5	1		*BONNET STAND	Not Damaged	127.90 FL	*- FL
6	1		*BONNET HINGE	Bent	210.00 FL	*128.00 FL
7	1		*FR GRILLE BADGE RED	Missing	133.00 FL	*27.40 FL
8	1		*FR BUMPER SIDE RETAINER	Necessary	188.60 FL	*90.00 FL
9	1		*FR BUMPER REINFORCEMENT	Missing	433.70 FL	*377.90 FL
10	1		*FR BUMPER UNDER COVER	Missing	371.00 FL	*153.80 FL
11	1		*HEADLAMP RH	Broken	952.50 FL	*790.40 FL
12	1		*HEADLAMP LH	Broken	952.50 FL	*790.40 FL
13	1		*HEADLAMP LOWER BRACKET RH	Broken	120.00 FL	*72.80 FL
14	1		*HEADLAMP LOWER BRACKET LH	Broken	120.00 FL	*72.80 FL
15	1		*SUPPORT PANEL	Bent	505.40 FL	*505.40 FL
16	1		*SUPPORT PANEL TOP GARNISH	Broken	277.40 FL	*188.90 FL
17	1		*SUPPORT PANEL TOP STOPPER	Missing	60.00 FL	*60.00 FL
18	1		*BATTERY TOP BRACKET	Dented	95.00 FL	*36.40 FL
19	1		*BATTERY LOWER TRAY	Dented	199.60 FL	*95.30 FL
20	1		*BATTERY LOWER TRAY BRACKET	Dented	184.20 FL	*66.10 FL
21	1		*FR CHASSIS SUB FRAME RH	Not Damaged	765.40 FL	*- FL
22	1		*OUTER TEMPERATURE SENSOR	Not Damaged	258.60 FL	*- FL
23	1		*AIR BAG IMPACT SENSOR	Not Damaged	620.00 FL	*- FL
24	1		*HORN	Broken	240.00 FL	*120.00 FL
25	1		*AIR CON CONDENSER	Broken	862.80 FL	*704.40 FL
26	1		*AIR CON CONDENSER TOP RUBBER	Missing	87.50 FL	*87.50 FL
27	1		*AIR CON CONDENSER TOP MOUNTING	Missing	60.00 FL	*60.00 FL
28	1		*AIR CON CONDENSER TOP MOUNTING BRACKET	Broken	110.00 FL	*60.00 FL
29	1		*AIR CON CONDENSER LOWER MOUNTING	Broken	60.00 FL	*60.00 FL
30	1		*AIR CON FAN COWLING	Broken	223.10 FL	*85.60 FL
31	1		*AIR CON FAN MOTOR	Short Circuit	365.40 FL	*365.40 FL
32	1		*AIR CON FAN BLADE	Not Damaged	92.40 FL	*- FL
33	1		*AIR CON PIPE	Bent	279.10 FL	*196.00 FL
34	1		*AIR CON SUCTION PIPE	Bent	431.00 FL	*212.00 FL
35	1		*AIR CON DISCHARGE PIPE	Bent	459.00 FL	*247.00 FL
36	1		*RADIATOR	Broken	1,382.60 FL	*1,382.60 FL
37	1		*RADIATOR TOP MOUNTING	Necessary	70.00 FL	*70.00 FL
38	1		*RADIATOR TOP MOUNTING BRACKET	Necessary	130.00 FL	*30.00 FL
39	1		*RADIATOR LOWER MOUNTING	Necessary	70.00 FL	*30.00 FL
40	1		*RADIATOR TOP HOSE	Necessary	78.90 FL	*78.90 FL
41	1		*RADIATOR LOWER HOSE	Necessary	82.30 FL	*82.30 FL
42	1		*RADIATOR SPARE TANK	Broken	155.30 FL	*86.50 FL
43	1		*RADIATOR FAN COWLING	Repeated	219.00 FL	*- FL
44	1		*RADIATOR FAN MOTOR	Repeated	365.40 FL	*- FL
45	1		*RADIATOR FAN BLADE	Bent	95.70 FL	*95.70 FL
46	1		*FAN COWLING MOTOR RELAY	Short Circuit	437.00 FL	*437.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*WIPER TANK	Not Damaged	190.00 FL	*- FL
48	1		*WIPER TANK MOTOR	Not Damaged	102.30 FL	*- FL
49	1		*WIPER TANK NECK	Not Damaged	89.00 FL	*- FL
50	1		*AIR CLEANER BOX ASSY	Not Damaged	652.40 FL	*- FL
51	1		*WIPER GARNISH	Not Damaged	397.50 FL	*- FL
52	1		*WIPER SIDE GARNISH	Not Damaged	180.00 FL	*- FL
53	1		*ALTERNATOR	Not Damaged	1,316.00 FL	*- FL
54	1		*BONNET	Broken	2,000.00 FS	*895.30 FS
55	1		*BONNET INSULATOR CLIP	Missing	40.00 FS	*20.00 FS
56	1		*BONNET STAND CLIP	Necessary	20.00 FS	*20.00 FS
57	1		*FR CAR PLATE W COVER	Missing	80.00 FS	*50.00 FS
58	1		*FR BUMPER	Missing	1,500.00 FS	*738.00 FS
59	1		*FR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
60	1		*FR BUMPER GRILLE	Missing	600.00 FS	*236.00 FS
61	1		*FR BUMPER UNDER COVER CLIP	Necessary	40.00 FS	*20.00 FS
62	1		*SUPPORT PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
63	1		*SUPPORT PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*30.00 FS
64	1		*BATTERY	Broken	220.00 FS	*80.00 FS
65	1		*FR CHASSIS SUB FRAME SEALANT	Not Necessary	80.00 FS	*- FS
66	1		*RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS
67	1		*ENGINE UNDER COVER CLIP	Repeated	40.00 FS	*- FS
68	1		*WIPER GARNISH CLIP	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,801.30	10,625.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,382.26	1,689.18
Total Parts (\$\$)	18,419.04	8,936.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	250.00	0.00
4	TO APPLY ANTI-RUST AND TUFF COAT	New	200.00	0.00
5	REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	New	180.00	100.00
6	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	150.00	120.00
7	TO RESET AND REPROGRAM ABS SYSTEM AND FUNCTION	New	500.00	0.00
			Gross Labour Cost (\$)	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >