



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 6079U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LIFT FORK CRANE MAIN MEMBER	DAMAGED	4,500.00	4,500.00
1	LIFT FORK MAIN HYDRAULIC CYLINDER JACK	DAMAGED	1,800.00	1,800.00
1	LIFT FORK MAIN SLIDING MEMBER CYLINDER JACK	DAMAGED	1,600.00	1,600.00
1	LIFT FORK OUTER MAIN MEMBER SLIDING MEMBER (CAN'T SEE DAMAGED)	REPAIRABLE	1,800.00	-
1	LIFT FORK T MEMBER (CAN'T SEE DAMAGED)	REPAIRABLE	2,800.00	-
1	LIFT FORK T MEMBER HYDRAULIC CYLINDER JACK	SERVICEABLE	1,600.00	-
1	REAR NUMBER PLATE	BENT	35.00	35.00
1	REAR NUMBER PLATE LAMP (CAN'T SEE DAMAGED)	NOT NECESSARY	67.00	-
			14,202.00	7,935.00
<b>LABOUR</b>				
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.			1,800.00	1,000.00
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.			200.00	-
TO DISMANTLE AND REPLACED LIFTING FORK ASSY, PIVOT PIN, HYDRAULIC CYLINDER, JACKS, HYDRAULIC HOSE AND ETC, AND TO CHECK AND ALIGN SYSTEM FOR PROPER OPERATION.			3,000.00	1,000.00
TO CHECK WIRING SYSTEM AND LIGHT.			150.00	70.00
			5,150.00	2,070.00
<b>GRAND TOTAL</b>			<b>19,352.00</b>	<b>10,005.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,000.00</b>

Report Ref No. CS1/LAW21009656/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.