LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21009657/ATCE2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 **Date:** 11/11/2021

REFERENCE

Insured/Claimant: LIM TEONG GUAN Policy No: 1800111711

Date of Loss: 07/09/2021 Nature of Claim: OD Claim No: 1039572980SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME1364M

Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD876713

Reg. Date: 19/09/2018 (Man. Year: 2018) Chassis No: WAUZZZ8U1JR100966

Colour: Black Odometer: 39428 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$108,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,577.00	3,083.12	3,493.88	53.12
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,752.00	2,122.00	7,630.00	78.24
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	16,329.00	5,205.12	11,123.88	68.12
	- Excess (S\$)	400.00	400.00	0.00	0.00
	(S\$)	15,929.00	4,805.12	11,123.88	69.83
	+ GST 7.00/7.00% (S\$)	1,115.03	336.36	778.67	69.83
	Nett Amount (S\$)	17,044.03	5,141.48	11,902.55	69.83

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

The image of the im

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	2,909.00 FS	*2,327.20 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	172.00 FS	*137.20 FS
3	1		*REAR DOOR SEAL BRACKET - LH	Not Necessary	18.00 FS	*- FS
4	3		*GROMMET	Not Necessary	8.00 FS	*-FS
5	1		*REAR DOOR ATTACHMENT PART	Not Necessary	218.00 FS	*- FS
6	1		*REAR DOOR CATCH - LH	Not Necessary	120.00 FS	*-FS
7	2		*FRONT AND REAR DOOR SOUL COVER - LH	Cut	514.00 FS	*410.40 FS
8	1		*REAR WHEEL ARCH COVER - LH / RH	N/S Cut	516.00 FS	*206.40 FS
9	1		*REAR SILL PANEL SEAL - LH	Not Necessary	65.00 FS	*- FS
10	1		*REAR SPOILER	Not Necessary	475.00 FS	*-FS
11	1		*REAR ALUMINIUM RIM - LH	Not Necessary	1,262.00 FS	*- FS
12	1		*SUNDRIES	Necessary	300.00 FS	*1.92 FS
F=Fra	nchise	part. S=SpcN	lett.	-		
				Total Parts (S\$)	6,577.00	3,083.12
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW REAR BUMPER SPOILER. TO RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER, DOOR ENTRANCES AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	550.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, DOOR ENTRANCE AND LHS FRONT DOOR	New	5,000.00	1,100.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	ır Cost (S\$)	9,752.00	2,122.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >