

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI21009658/R1QF3N2**Date:** 04/10/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKX3776T**Insured Vehicle No :** YP2111U

Date of Loss: 10/09/2021

Nature of Claim:

TP

Claim No: CDMFG21001781

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKX3776T**

Make &amp; Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No: K24W72010064

Reg. Date: 09/12/2015 (Man. Year: 2015)

Chassis No: JHMRC1890GC200125

Colour: Grey

Odometer: 135528 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,270.00	5,354.40	3,915.60	42.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,320.00	2,080.00	61.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,670.00</b>	<b>6,674.40</b>	<b>5,995.60</b>	<b>47.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,300.00</b>		
<b>(S\$)</b>	12,670.00	5,300.00	7,370.00	58.17
<b>+ GST 7.00/7.00% (S\$)</b>	886.90	371.00	515.90	58.17
<b>Nett Amount (S\$)</b>	<b>13,556.90</b>	<b>5,671.00</b>	<b>7,885.90</b>	<b>58.17</b>

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: 15/09/2021 Inspected At:

Toh Ah Swee Spray Painting Co (HQ)

No 60, Jalan Lam Huat, #07-33/34 Carros Centre  
Singapore 737869

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
<b>Parts:</b>	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX3776T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER	Deformed	1,090.00 FL	*856.00 FL
2	2		*REFLECTOR L AND R	Serviceable	80.00 FL	*- FL
3	1		*BOOTLID	Bent	1,800.00 FL	*1,172.00 FL
4	1		*BOOTLID TAIL LAMP LHS	Cracked	715.00 FL	*400.00 FL
5	1		*BOOTLID TAIL LAMP RHS	Cracked	715.00 FL	*400.00 FL
6	1		*BOOTLID LOWER CHROME	Cracked	450.00 FL	*223.00 FL
7	1		*BOOTLID UPPER CHROME	Cracked	430.00 FL	*284.00 FL
8	1		*BOOTLID HYDRAULIC STAND RHS	Serviceable	300.00 FL	*- FL
9	1		*BOOTLID HYDRAULIC STAND LHS	Serviceable	300.00 FL	*- FL
10	1		*BOOTLID OPEN BUTTON	Serviceable	230.00 FL	*- FL
11	1		*WIPER	Scratched	95.00 FL	*50.00 FL
12	1		*REAR WINDSCREEN WITH MOULDING	Necessary	2,100.00 FL	*1,260.00 FL
13	1		*WIPER MOTOR	Not Working	580.00 FL	*298.00 FL
14	1		*REVERSE SENSOR	Not Working	480.00 FS	*200.00 FS
15	1		*RECORD CAMERA	Missing	480.00 FS	*400.00 FS
16	1		*REVERSE CAMERA	Cut	560.00 FS	*350.00 FS
17	1		*SOLAR FILM	Necessary	240.00 FS	*300.00 FS
18	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
19	1		*BOOTLID CENTRE LOCK	Serviceable	315.00 FL	*- FL
20	1		*BUZZER ASSY	Cracked	150.00 FL	*150.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,140.00</b>	<b>6,373.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,870.00	1,018.60
<b>Total Parts (\$\$)</b>	<b>9,270.00</b>	<b>5,354.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS,TO KNOCK OUT DENTS,TO STRAIGHTEN,ADJUST,CHECK,RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY.TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS.TO REPLACE AND ALIGN THE ABOVE PARTS	New	1,200.00	500.00
2	PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS	New	1,200.00	400.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	300.00	120.00
4	TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING & INSTALLATION RECORD CAMERA	New	600.00	200.00
5	TO REMOVE DAMAGED PARTS,TO KNOCK OUT DENTS,TO STRAIGHTEN,ADJUST,CHECK,RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY.TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS.TO REPLACE AND ALIGN THE ABOVE PARTS	New	100.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,400.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >