

ASS. RECD. BY:

REF:

LPC / 210096671Kb

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 3447C Yr Regn: 02, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 318i c.c. 1499Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 104768 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPE 32040K497929Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: B.S 215/60R16R: PirBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/9/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rm

The UIC / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 15/9/202

Date / Time Action / Instruction

27th 21 Rm @ 3700h Cadw

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

F. n/s

Others: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 201825799E)
TEL: 62589831
FAX: 62585349

Not Notified
1/1pm @ 3700/h
Resurvey After Paint
2 days

ESTIMATE REPAIR COST TO BMW (318-I) REG NO : SLA 3447 C

		S\$
1 PC	BUMPER (FRONT) <i>1392.42</i>	<i>Buol/cm</i> 1538.15 ✓
1 PC	BUMPER TOWING COVER (FRONT RIGHT)	<i>Pr</i> 59.64 X
1 PC	BUMPER FRONT LAMP COVER (FRONT RIGHT)	<i>dis/cm</i> 110.59 ✓
1 PC	HEADLAMP (FRONT RIGHT) <i>3068.40</i>	<i>cm</i> 3088.16 ✓

TOTAL	4796.54
LESS 10%	479.64
TOTAL	4316.90

LABOUR & MISC CHARGES

PANEL KNOCKING
SPRAY PAINTING
BODY CLIPS

	800.00	<i>2501</i>
	600.00	<i>2501</i>
<i>me</i>	100.00	<i>501</i>

TOTAL 5816.90

CARIS AUTOWORKS PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: