

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21009668/KEA3Q2**Date:** 25/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210071766
Claimant Vehicle No :	SHC5661Z	Insured Vehicle No :	SKJ7323P
Date of Loss:	12/09/2021	Nature of Claim:	TP
		Claim No:	4636562459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5661Z		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2J11626
Reg. Date:	26/02/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU703093869
Colour:	Metallic Pearl White/Red	Odometer:	32656 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,127.85	1,853.30	4,274.55	69.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,240.00	810.00	5,430.00	87.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,367.85	2,663.30	9,704.55	78.47
+ GST 7.00/7.00% (S\$)	865.75	186.43	679.32	78.47
Nett Amount (S\$)	13,233.60	2,849.73	10,383.87	78.47
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$113.42/day) (S\$)		340.26		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		3,347.47		
Global Sum Settlement (S\$)		3,340.00		

INSPECTION

Date of Assignment:	14/09/2021		
Date Inspected:	14/09/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Distorted	374.50 FL	*374.50 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	22.00 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	132.60 FL	*132.60 FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
8	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
9	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	339.60 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 LH	Scratched	261.00 FL	*261.00 FL
11	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
12	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Mtg Cracked	913.60 FL	*913.60 FL
13	1		*STAY, ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
14	1		*STAY, ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
15	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
16	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
17	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
18	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME ,NO.2	Necessary	54.60 FL	*54.60 FL
19	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	54.60 FL	*54.60 FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*50.00 FS
22	1		*TAIL LAMP CLIP	Not Necessary	65.00 FS	*- FS
23	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
24	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
25	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
26	1		*BOOT STICKER TRANSCAB	Necessary	100.00 FS	*30.00 FS
27	1		*BOOT STICKER 65553333	Necessary	100.00 FS	*30.00 FS
28	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
29	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
30	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,548.80	2,434.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,420.95	581.10
Total Parts (\$\$)	6,127.85	1,853.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			6,240.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >