

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009671/ETCN2**Date:** 16/11/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00029242100

Claimant Vehicle No : SLJ573T **Insured Vehicle No :** SJC2810G

Date of Loss: 03/07/2021 Nature of Claim: TP Claim No: SNM21D203906/C03

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ573T**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: LEB4262715

Reg. Date: 28/11/2016 (Man. Year: 2016) Chassis No: GP71043105

Colour: Silver Odometer: 381058 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,983.20	1,698.00	285.20	14.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	430.00	570.00	57.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,983.20	2,128.00	855.20	28.67
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	2,983.20	1,700.00	1,283.20	43.01
+ GST 7.00/7.00% (S\$)	208.82	119.00	89.82	43.01
Nett Amount (S\$)	3,192.02	1,819.00	1,373.02	43.01

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: 16/09/2021 Inspected At: Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros Centre
Singapore 737569

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Nov 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ573T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,350.00 FL	*1,350.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	660.00 FL	*660.00 FL
3	1		*FRONT BUMPER RH TOW COVER	Cruched	54.00 FL	*54.00 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Broken	21.00 FL	*21.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	294.00 FL	*- FL
6	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,459.00	2,115.00
- List Item Discount on L Items 20.00/20.00% (\$)	475.80	417.00
Total Parts (\$)	1,983.20	1,698.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	600.00	230.00
2	TO RESPRAY FRONT BUMPER	New	400.00	200.00
Gross Labour Cost (S\$)			1,000.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >