

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III21009673/UTF3N2**Date:** 27/09/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : XE5324Y **Insured Vehicle No :** GBH7499H

Date of Loss: 14/09/2021 Nature of Claim: TP Claim No: MFL2021D0004003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE5324Y**
 Make & Model: ISUZU CYZ52R, 15.7 D (M) Engine No: 6WG1439521
 Reg. Date: 14/11/2019 (Man. Year: 2019) Chassis No: JALCYZ52RK7000040
 Colour: Green Odometer: 82670 km
 Engine Capacity: 15681 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5(D/D)
 Front Left Side: Powertrac 6 mm Rear Left Side: Powertrac 6/66/6 mm
 Front Right Side: Powertrac 6 mm Rear Right Side: Powertrac 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,412.20	9,569.00	6,843.20	41.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,040.00	1,950.00	4,090.00	67.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,452.20	11,519.00	10,933.20	48.70
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	22,452.20	9,200.00	13,252.20	59.02
+ GST 7.00/7.00% (S\$)	1,571.65	644.00	927.65	59.02
Nett Amount (S\$)	24,023.85	9,844.00	14,179.85	59.02

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: 16/09/2021 Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Sep 2021)	
Parts:	N/A	ISUZU CYZ52R 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5324Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DIESEL TANK BRACKET	Repair	576.00 FL	*- FL
2	1		*STAINLESS STEEL DIESEL TANK	Dented/Cracked	3,912.00 FL	*3,650.00 FL
3	1		*REAR BUMPER	Distorted	1,800.00 FS	*1,100.00 FS
4	1		*REAR BUMPER BRACKET-RH/LH	O/s Bent	1,780.00 FS	*400.00 FS
5	1		*REAR CENTER TANKER ALUMINIUM DISCHARGE	Bent	3,800.00 FS	*1,500.00 FS
6	1		*REAR RH TANKER ALUMINIUM DISCHARGE PLATE	Distorted	2,300.00 FS	*1,200.00 FS
7	1		*TAIL LAMP-RH	Cracked	120.00 FS	*120.00 FS
8	1		*SET REAR TAIL LAMP METAL FRAME	Bent	850.00 FS	*850.00 FS
9	1		*SET REAR SIDEGUARD-RH (DIESEL TANK)	Bent	1,100.00 FS	*1,100.00 FS
10	1		*REAR SPOTLIGHT-RH	Not Necessary	98.00 FS	*- FS
11	1		*REAR NUMBER PLATE	Bent	45.00 FS	*14.00 FS
12	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,861.00	9,934.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	448.80	365.00
Total Parts (\$\$)	16,412.20	9,569.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE & REFIX TO RENEW STAINLESS STEEL DIESEL TANK BRACKET	New	850.00	300.00
2	LABOUR TO CUT,DISMANTLE,WELD & RENEW REAR BUMPER & REAR BRACKET }	New	680.00	400.00
3	LABOUR TO CUT & WELD & RENEW TAIL LAMP METAL FRAME & REAR SIDEGUARD }	New	680.00	0.00
4	LABOUR TO REWIRE & CONNECT TAIL LAMP & FOG LAMP & CAMERA	New	380.00	50.00
5	TO RUST PROOFING ON AFFECTED AREA	New	650.00	0.00
6	TO SPRAY PAINTING ON ALL AFFECTED AREA	New	1,500.00	400.00
7	LABOUR TO RENEW & WELD ALUMINIUM CENTER & REAR RH DISCHARGE	New	1,300.00	800.00
Gross Labour Cost (\$)			6,040.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >