

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21009676/NQF3E2**Date:** 27/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070126253
Claimant Vehicle No :	SLJ977L	Insured Vehicle No :	SMU8690R
Date of Loss:	13/09/2021	Nature of Claim:	TP
		Claim No:	6219440064SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ977L	Engine No:	A0800124N20B20A
Make & Model:	BMW 328I, 2.0 (A)	Chassis No:	WBA3A52030F253652
Reg. Date:	12/03/2012 (Man. Year: 2012)	Odometer:	82616 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R19	Rear Tyre Size:	225/40 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/09/2021	
Date Inspected:	16/09/2021 Inspected At:	DREAMWORK GARAGE (HQ) 25 KAKI BUKIT ROAD 4 #06-55, SYNERGY @ KB Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$35,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT RH DOOR OUTER HANDLE	Repair	0.00 F	*- F
3	1		*REAR RH DOOR	Buckled	0.00 F	*- F
4	1		*REAR RH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
5	1		*REAR RH DOOR GLASS REGULATOR MOTOR	* Check	0.00 F	*- F
6	1		*REAR RH DOOR RUBBER	Necessary	0.00 F	*- F
7	1		*REAR RH DOOR OUTER HANDLE	Repair	0.00 F	*- F
8	1		*REAR RH DOOR LOCK	* Check	0.00 F	*- F
9	1		*REAR BUMPER	Repair	0.00 F	*- F
10	1		*REAR BUMPER SIDE RETAINER RH	* Check	0.00 F	*- F
11	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
12	1		*REAR RH FENDER	Repair	0.00 F	*- F
13	1		*REAR RH FENDER INNER SHIELD	Torn	0.00 F	*- F
14	1		*REAR RH WHEEL RIM	Cut	0.00 F	*- F
15	1		*REAR RH WHEEL BEARING	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >