



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2358A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LICENSE PLATE WITH CASING (SN)	BENT	50.00	50.00
1	BONNET (SN)	TO REPAIR SEE LABOUR	819.00	-
1	BONNET LOCK (SN)	SERVICEABLE	70.00	-
1	LH HEADLIGHT ASSY (SN)	NOT NECESSARY	564.00	-
1	RH HEADLIGHT ASSY (SN)	CRACKED	537.00	537.00
1	RH FRONT FENDER (SN)	TO REPAIR SEE LABOUR	1,128.00	-
1	RH WHEEL HOUSING MUD (SN)	NOT NECESSARY	200.00	-
10	RIVET WHEEL HOUSE (SN)	NECESSARY	10.00	10.00
1	UPR MLDG RADIATOR GR (SN)	CRACKED	262.00	262.00
1	RADIATOR GRILLE CHRO (SN)	CRACKED	255.00	255.00
1	CTR MLDG RADIATOR GR (SN)	CRACKED	162.00	162.00
1	LWR OTR STONE GUARD (SN)	TORN	397.00	397.00
1	FRONT BUMPER (SN)	DISTORTED	856.00	856.00
10	RIVET BUMPER (SN)	NECESSARY	10.00	10.00
1	SET BRACKETS BUMPER (SN)	BENT	75.00	75.00
1	TOW HOOK COVER (SN)	TORN	60.00	60.00
1	RH BUMPER MOULDING (SN)	DISTORTED	241.00	241.00
2	O/S FRONT LIGHT DRL (SN)	O/S CRACKED	444.00	222.00
2	FOG HEADLIGHT (SN)	O/S CRACKED	248.00	124.00
4	SENSOR FRONT (SN)	O/S SHORTED (1PC ONLY)	976.00	244.00
1	CTR INR STONE GUARD (SN)	DISTORTED	302.00	302.00
1	INR MLDG BUMPER BRAC (SN)	DISTORTED	256.00	256.00
1	BUMPER REINFORCEMENT (SN)	DISTORTED	507.00	507.00
1	FRONT FRAME SUPPORT (SN)	CRACKED	325.00	325.00
1	LH AIR BULKHEAD (SN)	TORN	92.00	92.00
1	RH AIR BULKHEAD (SN)	TORN	92.00	92.00
1	HARNESS WIRE FOG LIG (SN)	NOT NECESSARY	209.00	-
1	MOTOR-DRIVN FAN (SN)	JAMMED	432.00	432.00
1	FUSE RADIATOR FAN (SN)	NOT NECESSARY	15.00	-

Report Ref No. CS/FCI21009680/Uvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR ASSY (SN)	NOT NECESSARY	544.00	-
1	CONDENSER ASSY (SN)	NOT NECESSARY	796.00	-
1	COOLANT (SN)	NECESSARY	104.00	104.00
1	WASHER TANK EQUIPE (SN)	NOT NECESSARY	232.00	-
1	HARNESS WIRE LOOM DE (SN)	NOT NECESSARY	323.00	-
			11,593.00	5,615.00
	LABOUR			
	DIAGNOSTIC / SCANNING.		250.00	250.00
	TO CHECK ALL LIGHTING / WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS.		100.00	80.00
	TO REMOVE & REPLACE RADIATOR ASSY, COOLING FAN AND CONDENSER. TO TOP UP AIRCON GAS AND COOLANT.		180.00	180.00
	TO REPLACE FRONT BONNET, HEADLAMPS, RH FENDER, WHEEL HOUSE, RADIATOR GRILLE, FRONT BUMPER, BRACKETS, SENSORS, FOG LIGHTS, INR FRAME, ETC. TO REMOVE & REPLACE FRONT SUPPORT PANEL. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF BONNET AND RH FRONT FENDER.		4,480.00	1,920.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS (FRONT BONNET, RH FENDER, FRONT BUMPER, GRILLE MLDGS).		2,750.00	2,200.00
	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS.		200.00	100.00
			7,960.00	4,730.00
GRAND TOTAL			19,553.00	10,345.00
RECOMMENDED COST OF REPAIRS				10,345.00
LESS EXCESS				-600.00
NETT LIABILITY				9,745.00

Report Ref No. CS/FCI21009680/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.