



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQV 3804

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP (CONSISTENT)	CRACKED	350.00	295.00
1	FRONT HEADLAMP BRACKET (CONSISTENT)	NECESSARY	150.00	90.00
1	FRONT HEADLAMP FAIRING (CONSISTENT)	SCRATCHED	280.00	280.00
2	SIGNAL LAMP (CONSISTENT)	CUT	160.00	160.00
1	WINDSHIELD (CONSISTENT)	SCRATCHED	150.00	135.00
1	FRONT FENDER (CONSISTENT)	SCRATCHED	250.00	105.00
1	WING MIRROR (CONSISTENT)	MISSING	120.00	120.00
1	HANDLE BAR (CONSISTENT)	BENT	250.00	125.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	90.00	35.00
1	CLUTCH LEVER (CONSISTENT)	SCRATCHED	90.00	35.00
1	SET BALANCER (CONSISTENT)	SCRATCHED	120.00	95.00
1	FRONT FORK BRACKET (CONSISTENT)	CRACKED	180.00	180.00
1	GEAR PEDAL (CONSISTENT)	CUT	90.00	45.00
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	90.00	35.00
1	RADIATOR (CONSISTENT)	DEFORMED	650.00	280.00
1	FOOTREST (CONSISTENT)	SCRATCHED	120.00	70.00
1	FOOTREST RUBBER (CONSISTENT)	NOT NECESSARY	60.00	-
1	FOOTREST BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	80.00	-
1	LOWR FAIRING LH (CONSISTENT)	SCRATCHED	350.00	190.00
1	FAIRING INNER LH (CONSISTENT)	MISSING	350.00	143.90
1	FAIRING OUTER LH (CONSISTENT)	MISSING	350.00	225.00
2	EXHAUST COVER (CONSISTENT)	SCRATCHED	280.00	58.00
	LESS 10% DISCOUNT		-461.00	-270.19
			4,149.00	2,431.71
1	SET FRONT FORK (LOCAL REPAIR) (SN)(CONSISTENT)	BENT	600.00	80.00
	LESS 10% DISCOUNT		-60.00	-
			540.00	80.00

Report Ref No. CC4/ASM21009686/Vgs3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BOX (SN)(CONSISTENT)	SCRATCHED	300.00	180.00
1	FORK OIL SEAL (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
1	FORK OIL (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
1	GEAR SHAFT OIL (SN)(CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT NUMBER PLATE (SN)(CONSISTENT)	NECESSARY	50.00	20.00
			440.00	200.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		60.00	30.00
	TO R&R SUSPENSION ,HANDLE BAR ,HEADLAMP & FAIRING.INCLUSIVE OF THE REPAIR OF FOOTREST BRACKET .		600.00	200.00
	TO SPRAY FENDER ,FAIRINGS AND AFFECTED AREAS .	NOT NECESSARY	600.00	-
			1,260.00	230.00
<b>GRAND TOTAL</b>			<b>6,389.00</b>	<b>2,941.71</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CC4/ASM21009686/Vgs3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.