

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20007021/T1RA3Q2-1

Date:

30/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100501045

Claimant Vehicle No : SHB4171H**Insured Vehicle No :**

SLL1644E

Date of Loss: 04/07/2020

Nature of Claim:

TP

Claim No:

5154192558SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHB4171H

Make & Model:

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDFU562232

Reg. Date:

05/11/2015 (Man. Year: 2015)

Chassis No:

KMHLB41UMGU080371

Colour:

Blue

Odometer:

575558 km

Engine Capacity:

1685 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60R16

Rear Tyre Size:

205/60R16

Front Left Side:

West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side:

West Lake 6 mm

Rear Right Side:

West Lake 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,905.70	4,175.78	4,729.92	53.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,420.00	900.00	38.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,225.70	5,595.78	5,629.92	50.15
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	11,225.70	4,500.00	6,725.70	59.91
+ GST 7.00/7.00% (S\$)	785.80	315.00	470.80	59.91
Nett Amount (S\$)	12,011.50	4,815.00	7,196.50	59.91
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$55.34/day) (S\$)		276.70		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,349.19		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment: 06/07/2020

Date Inspected: 06/07/2020

Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
2	2		*BOOTLID HINGE (LH/RH)	Repair	284.60 FL	*- FL
3	1		*BOOTLID LOCK UPPER	Bent	114.90 FL	*114.90 FL
4	1		*BOOTLID LOCK LOWER	Repair	31.70 FL	*- FL
5	1		*BOOTLID H EMBLEM	Necessary	28.70 FL	*28.70 FL
6	1		*BOOTLID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
7	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
8	2		*BOOTLID LAMP(LH/RH)	Not Necessary	1,131.20 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
10	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	160.60 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
12	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Not Necessary	71.20 FL	*- FL
14	1		*REAR BUMPER SPONGE	Cracked	119.50 FL	*119.50 FL
15	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	*228.00 FL
16	2		*REAR BUMPER REFLECTOR RH/LH	Not Necessary	64.00 FL	*- FL
17	2		*TAIL LAMP (LH/RH)	Not Necessary	1,395.60 FL	*- FL
18	1		*REAR PANEL	Bent	526.70 FL	*526.70 FL
19	1		*REAR PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
20	1		*REAR PANEL LOWER PANEL	Repair	495.50 FL	*- FL
21	1		*SPARE TYRE HOLDER	Not Necessary	248.00 FL	*- FL
22	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
23	1		*EXHAUST SILENCER RH/LH	Repair	1,935.40 FL	*- FL
24	1		*BOOTLID COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
25	1		*BOOTLID 65521111	Necessary	30.00 FS	*30.00 FS
26	1		*BOOTLID APPS	Necessary	40.00 FS	*40.00 FS
27	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
28	1		*REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,060.70	5,148.30
- List Item Discount on L Items 20.00/20.00% (\$)	2,155.00	972.52
Total Parts (\$)	8,905.70	4,175.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	60.00
5	REMOVE /REFIX REVERSE SENSOR	New	120.00	30.00
6	REMOVE/REFIX EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$)			2,320.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >