

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009691/AVCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant:	ADLI LIM @ ADLI BIN ADAM	Policy No:	1900170399	
Date of Loss:	13/09/2021	Nature of Claim:	OD	Claim No: 2127023183SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8279M		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK084456
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF4XKA089565
Colour:	Grey	Odometer:	47407 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,117.00	13,444.48	6,672.52	33.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,322.00	5,672.00	3,650.00	39.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,439.00	19,116.48	10,322.52	35.06
- Excess (S\$)	3,550.00	3,550.00	0.00	0.00
(S\$)	25,889.00	15,566.48	10,322.52	39.87
+ GST 7.00/7.00% (S\$)	1,812.23	1,089.65	722.58	39.87
Nett Amount (S\$)	27,701.23	16,656.13	11,045.10	39.87

INSPECTION

Date of Assignment:	16/09/2021		
Date Inspected:	15/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
6	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	126.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,184.00 FS	*1,747.20 FS
8	1		*AIR GUIDE GRILLE-RH	Not Necessary	365.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT FOAM PIECE	Cracked	124.00 FS	*99.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BAR	Dented	845.00 FS	*675.60 FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
13	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
14	1		*FRONT BUMPER BRACKET	Damaged	137.00 FS	*109.60 FS
15	2		*FRONT BUMPER SUPPORT-LH/RH	Damaged	58.00 FS	*44.96 FS
16	4		*POP RIVET	Necessary	4.00 FS	*2.56 FS
17	1		*HORN-RH	Not Necessary	126.00 FS	*- FS
18	1		*HORN BRACKET-RH	Not Necessary	29.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(Npa)			
20	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
21	1		*FRONT BONNET	Dented	3,246.00 FS	*2,596.80 FS
22	1		*FRONT BONNET ATTACHMENT PART	Not Necessary	412.00 FS	*- FS
23	1		*FRONT BONNET IMPACT PROTECTION-LH/RH/CENTER	Necessary	84.00 FS	*65.68 FS
			(3 Pcs)			
24	1		*FRONT BONNET RELEASE CABLE	Not Necessary	58.00 FS	*- FS
25	1		*FRONT BONNET HOOD RELEASE	Not Necessary	14.00 FS	*- FS
26	1		*FRONT BONNET BOWDEN CABLE-CENTER	Not Necessary	58.00 FS	*- FS
27	1		*FRONT BONNET CABLE COVER	Not Necessary	10.00 FS	*- FS
28	1		*FRONT BONNET STRIKER	Not Necessary	50.00 FS	*- FS
29	1		*FRONT BONNET LOCK	Not Necessary	214.00 FS	*- FS
30	1		*FRONT HEADLIGHT-RH	Cracked	7,693.00 FS	*6,154.40 FS
31	1		*FRONT HEADLIGHT LIFT CYLINDER-RH	Not Necessary	210.00 FS	*- FS
32	1		*FRONT HEADLIGHT LIFT CYLINDE HOSE	Not Necessary	93.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE-RH OUTER	Cracked	28.00 FS	*22.32 FS
34	1		*RADIATOR AIR GUIDE-RH INNER	Cracked	12.00 FS	*9.44 FS
35	1		*RADIATOR AIR DUCT-RH UPPER	Not Necessary	16.00 FS	*- FS
36	1		*RADIATOR AIR DUCT-RH LOWER	Not Necessary	22.00 FS	*- FS
37	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
38	1		*SUNDRIES	Necessary	300.00 FS	*8.48 FS
39	1		*OUTER TEMP, SENSOR BRACKET	Damaged	19.00 FS	*14.56 FS
			(Supplementary)			
40	1		*RADIATOR AIR GUIDE-LH	Torn	12.00 FS	*9.44 FS
			(Supplementary)			
41	1		*FRONT REINFORCEMENT BEAM BRACKET-RH	Bent	228.00 FS	*182.00 FS
			(Supplementary)			
42	1		*COOLANT	Necessary	266.00 FS	*212.64 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,117.00** **13,444.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND REINSTALL AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR. TO CHECK ON ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (Supplementary)	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET. (Supplementary)	New	2,800.00	1,250.00
Gross Labour Cost (\$\$)			9,322.00	5,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >