

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009692/ATCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant: ORIENTAL SHEET PILING PTE LTD
Date of Loss: 14/05/2021

Policy No: 2070171472
Nature of Claim: OD Claim No: 0912885085SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ6633P**
Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB047111
Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: WAUZZZF16KD006122
Colour: Grey Odometer: 42517 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$280,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R22 Rear Tyre Size: 235/40R22
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,018.00	2,376.40	11,641.60	83.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,582.00	2,852.00	2,730.00	48.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,600.00	5,228.40	14,371.60	73.32
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	18,200.00	3,828.40	14,371.60	78.96
+ GST 7.00/7.00% (S\$)	1,274.00	267.99	1,006.01	78.96
Nett Amount (S\$)	19,474.00	4,096.39	15,377.61	78.96

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 15/09/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-UPPER	Repair	1,362.00 FS	*- FS
2	1		*REAR BUMPER-LOWER	Repair	2,669.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
4	1		*REAR BUMPER SIDE TRIM-LH	Not Necessary	86.00 FS	*- FS
5	1		*REAR BUMPER CENTER TRIM	Not Necessary	129.00 FS	*- FS
6	1		*REAR BUMPER FILLER TRIM-CENTER	Deformed	423.00 FS	*338.40 FS
7	1		*REAR BUMPER SPOILER-DARK CHROME MATT	Deformed	815.00 FS	*651.60 FS
8	1		*REAR EXHAUST TRIM PLATE-LH	Cut	95.00 FS	*75.84 FS
9	1		*REAR EXHAUST TRIM-LH	Cut	244.00 FS	*195.20 FS
10	1		*REAR BUMPER LOWER SPOILER	Deformed	575.00 FS	*460.00 FS
11	1		*REAR BUMPER DIFFUSER	Not Necessary	1,261.00 FS	*- FS
12	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	411.00 FS	*- FS
13	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,417.00 FS	*- FS
14	2		*REAR BUMPER SEAL-LH/RH	Not Necessary	28.00 FS	*- FS
15	1		*REAR BUMPER RETAINER PLATE	Not Necessary	182.00 FS	*- FS
16	1		*REAR BUMPER GUIDE SECTION-CENTER	Not Necessary	142.00 FS	*- FS
17	1		*REAR BUMPER GUIDE SECTION-LH LOWER	Not Necessary	75.00 FS	*- FS
18	1		*REAR BUMPER GUIDE SECTION-LH UPPER	Not Necessary	67.00 FS	*- FS
19	1		*RETAINER FOR AERIAL-LH	Not Necessary	26.00 FS	*- FS
20	1		*TELEPHONE AERIAL	Not Necessary	174.00 FS	*- FS
21	1		*REAR REFLECTOR LIGHT-LH	Not Necessary	136.00 FS	*- FS
22	1		*REAR SILENCER	Not Necessary	2,344.00 FS	*- FS
23	1		*REAR SILENCER MUFFLER CLAMP	Not Necessary	121.00 FS	*- FS
24	1		*REAR SILENCER HANGER	Not Necessary	60.00 FS	*- FS
25	2		*REAR WHEEL COVER-LH/RH	Necessary	756.00 FS	*602.40 FS
26	1		*SUNDRIES	Necessary	250.00 FS	*52.96 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	14,018.00	2,376.40
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
3	TO RESPRAY REAR BUMPER,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,200.00	1,700.00
4	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			5,582.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >