

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009696/ATCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant: ORIENTAL SHEET PILING PTE LTD
Date of Loss: 10/09/2021

Policy No: 2070171472
Nature of Claim: OD Claim No: 5805635169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ6633P**
Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB047111
Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: WAUZZZF16KD006122
Colour: Grey Odometer: 42517 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$280,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R22 Rear Tyre Size: 235/40R22
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,099.00	9,922.64	19,176.36	65.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,932.00	6,582.00	19,350.00	74.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,031.00	16,504.64	38,526.36	70.01
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	53,631.00	15,104.64	38,526.36	71.84
+ GST 7.00/7.00% (S\$)	3,754.17	1,057.32	2,696.85	71.84
Nett Amount (S\$)	57,385.17	16,161.96	41,223.21	71.84

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 15/09/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Dented	4,907.00 FS	*3,925.60 FS
2	1		*HEXAGON	Not Necessary	5.00 FS	*- FS
3	1		*OVAL HEAD SCREW	Not Necessary	4.00 FS	*- FS
4	1		*FRONT DOOR SEAL	Necessary	172.00 FS	*137.20 FS
5	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
7	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
8	1		*FRONT DOOR ATTACHMENT PART	Not Necessary	231.00 FS	*- FS
9	1		*FRONT DOOR CATCH-RH	Not Necessary	128.00 FS	*- FS
10	2		*HEXAGON	Not Necessary	5.00 FS	*- FS
11	1		*OVAL HEAD SCREW	Not Necessary	4.00 FS	*- FS
12	1		*FRONT DOOR HANDLE-RH	Cut	365.00 FS	*292.00 FS
13	1		*FRONT DOOR HANDLE CAP-RH	Not Necessary	40.00 FS	*- FS
14	1		*FRONT DOOR COVER-RH	Cut	507.00 FS	*407.20 FS
15	1		*REAR DOOR-RH	Distorted	4,907.00 FS	*3,925.60 FS
16	1		*REAR DOOR SEAL-RH	Necessary	172.00 FS	*137.20 FS
17	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
18	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
19	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
20	1		*FRONT DOOR ATTACHMENT PART	Not Necessary	231.00 FS	*- FS
21	1		*REAR DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
22	2		*HEXAGON	Not Necessary	5.00 FS	*- FS
23	1		*OVAL HEAD SCREW	Not Necessary	4.00 FS	*- FS
24	1		*REAR DOOR SEAL-RH INNER	Not Necessary	589.00 FS	*- FS
25	1		*REAR DOOR SEAL-RH OUTER	Necessary	253.00 FS	*202.00 FS
26	1		*SILL PANEL SEAL-RH	Not Necessary	253.00 FS	*- FS
27	1		*REAR DOOR SEAL BRACKET-RH	Not Necessary	43.00 FS	*- FS
28	1		*REAR DOOR HANDLE-RH	Cut	365.00 FS	*292.00 FS
29	1		*REAR DOOR HANDLE CAP-RH	Not Necessary	40.00 FS	*- FS
30	1		*REAR DOOR COVER-RH	Cut	507.00 FS	*405.60 FS
31	1		*REAR DOOR WHEEL COVER-RH	Cut	196.00 FS	*156.80 FS
32	1		*REAR SIDE PANEL FRAME-RH OUTER	Repair	8,415.00 FS	*- FS
33	1		*REAR SIDE WINDOW-RH	Not Necessary	946.00 FS	*- FS
34	2		*RIVET	Not Necessary	3.00 FS	*- FS
35	1		*PRIMER	Not Necessary	20.00 FS	*- FS
36	1		*REAR SILL TRIM STRIP-RH	Not Necessary	621.00 FS	*- FS
37	1		*FRONT SILL TRIM STRIP-RH	Not Necessary	787.00 FS	*- FS
38	2		*REAR WHEEL ARCH-LH/RH	Not Necessary	754.00 FS	*- FS
39	1		*WHEEL HOUSING LINER-RH (NPA)	Not Necessary	0.00 FS	*- FS
40	1		*SPOILER	Necessary	52.00 FS	*41.44 FS
41	1		*REAR MOUNTING BAR	Not Necessary	129.00 FS	*- FS
42	1		*WINDOW REGULATOR WITHOUT MOTOR-RH	Not Necessary	375.00 FS	*- FS
43	1		*WINDOW REGULATOR MOTOR-RH	Not Necessary	313.00 FS	*- FS
44	1		*DOOR INNER PANEL COVER-RH	Not Necessary	103.00 FS	*- FS
45	1		*STATIC MIXER	Not Necessary	8.00 FS	*- FS
46	1		*EPOXY ADHESIVE	Not Necessary	113.00 FS	*- FS
47	1		*ALUMINIUM POWDER	Not Necessary	573.00 FS	*- FS
48	1		*HARDENER	Not Necessary	210.00 FS	*- FS
49	1		*ALUMINIUM PRIMER	Not Necessary	212.00 FS	*- FS
50	1		*CLEANING BLOCK	Not Necessary	77.00 FS	*- FS
51	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
52	1		*ARCRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
53	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
54	1		*STONE CHIP	Repair	180.00 FS	*- FS

Report was unsubmitted during this print-out.

11/16/21, 1:22 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*REAR RIM-RH (NPA)	Cut	0.00 FS	*- FS
56	1		*REAR TYRE-RH (NPA)	Not Necessary	0.00 FS	*- FS
57	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					29,099.00	9,922.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AIR AND REAR LID KICK SENSOR	New	360.00	0.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR RHS SIDE 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	0.00
7	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE	New	900.00	760.00
8	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	New	1,800.00	0.00
9	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW RHS FRONT DOOR AND RHS REAR DOOR.TO CUT OUT AND WELD RHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,100.00	1,800.00
10	TO RESPRAY RHS REAR FENDER,RHS REAR DOOR,RHS FRONT DOOR,TWO DOOR COVERS,TWO DOOR HANDLES,RHS SILL PANEL,DRAIN CHANNEL,ROOF CHANNEL,DOOR ENTRABCE REAR END PANELLING,RHS REAR DOOR WHEEL ARCH AND BOTH REAR WHEEL ARCH TRIMS	New	8,900.00	3,550.00
11	TO CARRY OUT ALUMINIUM PRIMER WORK	New	900.00	0.00
12	TO RENEW RHS REAR RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			25,932.00	6,582.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >