

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009698/DTCN2**Date:** 17/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00077472003

Claimant Vehicle No : SLU8494C **Insured Vehicle No :** SKL574S

Date of Loss: 14/09/2021 Nature of Claim: TP Claim No: SNM21D205214/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8494C**

Make & Model: SUBARU IMPREZA, 1.5 R AWD 4AT ABS AIRBAG (A) Engine No: EL15D619600

Reg. Date: 13/02/2009 (Man. Year: 2008) Chassis No: JF1GE3KS59G003734

Colour: White Odometer: 155583 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm

Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,768.48	5,082.56	30,685.92	85.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,670.00	1,780.00	4,890.00	73.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	42,438.48	6,862.56	35,575.92	83.83
Approved Total (Overridden) (\$\$)		5,500.00		
(\$\$)	42,438.48	5,500.00	36,938.48	87.04
+ GST 7.00/7.00% (\$\$)	2,970.69	385.00	2,585.69	87.04
Nett Amount (\$\$)	45,409.17	5,885.00	39,524.17	87.04

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 17/09/2021 Inspected At: C.S. Ong Auto Pte Ltd (AMK)
10 Ang Mo Kio Industrial Park 2A, #02-16, AMK
Auto Point
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Dec 2021)

Parts: 143 SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU8494C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,380.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	310.00 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	150.00 FL	*- FL
4	1		*HEAD LAMP LH/RH	O/s Broken/N/s Not Necessary	5,082.00 FL	*874.30 FL
5	1		*HEAD LAMP LOWER BRACKET RH	Broken	198.00 FL	*95.70 FL
6	1		*HEAD LAMP ECU RH	Not Necessary	1,180.00 FL	*- FL
7	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,992.00 FL	*- FL
8	1		*FRONT GRILLE	Mounting Cracked	682.00 FL	*597.30 FL
9	1		*FRONT GRILLE BASE	No such part	701.00 FL	*- FL
10	1		*FRONT GRILLE CHROME	No such part	591.00 FL	*- FL
11	1		*FRONT BUMPER	Distorted/Cracked	1,401.00 FL	*654.30 FL
12	1		*FRONT BUMPER FOG LAMP RH	Cracked	410.00 FL	*404.80 FL
13	1		*FRONT BUMPER FOG LAMP HOLDER RH	No such part	278.00 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,930.00 FL	*- FL
15	1		*FRONT BUMPER SIDE RETAINER LH/RH	Os Dislodged/Ns Not Necessary	390.00 FL	*38.00 FL
16	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	421.00 FL	*- FL
17	1		*FRONT BUMPER SPONGE	Not fitted	423.00 FL	*- FL
18	1		*FRONT REINFORCEMENT BAR	Dented	1,292.00 FL	*388.10 FL
19	1		*FRONT SUPPORT PANEL	Bent/Dented	2,680.00 FL	*695.70 FL
20	1		*A/C CONDENSOR	Not Necessary	1,689.00 FL	*- FL
21	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	931.00 FL	*- FL
22	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	401.00 FL	*- FL
23	1		*RADIATOR ASSY	Not Necessary	2,194.00 FL	*- FL
24	1		*RADIATOR FAN MOTOR	Not Necessary	452.00 FL	*- FL
25	1		*RADIATOR FAN BLADE	Not Necessary	201.00 FL	*- FL
26	1		*RADIATOR FAN SOWLING	Not Necessary	499.00 FL	*- FL
27	1		*FRONT FENDER RH	Dented	1,429.00 FL	*570.50 FL
28	1		*FRONT FENDER INNER SHIELD RH	Torn	251.00 FL	*110.30 FL
29	1		*FRONT FENDER LAMP RH	Not Necessary	295.00 FL	*- FL
30	1		*FRONT WHEEL BEARING RH	Damaged	280.10 FL	*280.40 FL
31	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	281.00 FL	*- FL
32	1		*FRONT KNUCKLE ARM RH	Distorted	895.00 FL	*321.10 FL
33	1		*FRONT LOWER ARM RH	Distorted	590.00 FL	*333.10 FL
34	1		*FRONT ABSORBER RH	Distorted	711.00 FL	*302.10 FL
35	1		*FRONT STABILIZER LINK RH	Not Necessary	159.00 FL	*- FL
36	1		*FRONT STABILIZER BAR	Not Necessary	310.00 FL	*- FL
37	1		*FRONT TIE ROD RH	Not Necessary	210.00 FL	*- FL
38	1		*FRONT TIE ROD END RH	Not Necessary	241.00 FL	*- FL
39	1		*STEERING RACK & PINION ASSY	Not Necessary	2,890.00 FL	*- FL
40	1		*DRIVE SHAFT RH	Not Necessary	2,195.00 FL	*- FL
41	1		*FRONT DOOR RH	Not Necessary	1,874.00 FL	*- FL
42	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	210.00 FL	*- FL
43	1		*FRONT DOOR BLACK PLASTIC RH	Not Necessary	94.00 FL	*- FL
44	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
46	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

12/17/21, 2:47 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
48	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS
50	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*COOLANT	Not Necessary	100.00 FS	*- FS
52	1		*SPORT RIM	Cut	1,400.00 FS	*500.00 FS
53	1		*TYRE	Not Necessary	400.00 FS	*- FS
54	1		*FRONT NO PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					44,123.10	6,215.70
- List Item Discount on L Items 20.00/20.00% (\$)					8,354.62	1,133.14
Total Parts (\$)					35,768.48	5,082.56
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
3	TO TUFF COAT DAMAGED AREAS	New	200.00	40.00
4	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
8	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$)			6,670.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >