

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21009702/NVF3N2**Date:** 04/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000076
Claimant Vehicle No :	SHA9380T	Insured Vehicle No :	SLP4811Z
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	M2104324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9380T	Engine No:	G4LEJU080153
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU107280
Reg. Date:	21/08/2018 (Man. Year: 2018)	Odometer:	277614 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	DURATURN 3 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	DURATURN 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,737.20	633.60	1,103.60	63.53
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	760.00	630.00	130.00	17.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,508.20	1,274.60	1,233.60	49.18
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,508.20	1,000.00	1,508.20	60.13
+ GST 7.00/7.00% (S\$)	175.57	70.00	105.57	60.13
Nett Amount (S\$)	2,683.77	1,070.00	1,613.77	60.13

INSPECTION

Date of Assignment:	16/09/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	16/09/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA9380T)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	-	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	-	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	-	*- FL
5	1		*REAR BUMPER TOWING COVER	Serviceable	98.80 FL	-	*- FL
6	1		*REAR BUMPER FOG LAMP	Serviceable	201.50 FL	-	*- FL
7	1		*REAR BUMPER REVERSE SENSOR	Serviceable	180.00 F	-	*- FS
8	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 FS
9	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS
10	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,062.75	728.25
- List Item Discount on L Items 20.00/20.00% (S\$)	325.55	94.65
Total Parts (S\$)	1,737.20	633.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
			Gross Labour Cost (\$\$)	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >