

ASSIGNMENT

From: Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$1

) Photos

) Others

TOTAL

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Wonder / Jammed / Leaked / Burnt or

Brake: Wonder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

LTA at 25 2019 \$ 17856

28/9/21 9/2 \$ 535.72 confirmed with Susan.



LIU'S BROTHER AUTO ENGINEERING WORKSHOP
No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbroy@gmail.com

Invoice/Ref No: YN8594E190527

Estimate

Customer

Name: MS First Capital Insurance Limited

Date: 15-09-21

Address Motor Claims Department

Vehicle No: YN8594E

36 Robinson Road #16-01

Model/Make: Mitsubishi

City House

Singapore 068877

Canter FEB21CR3SDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tail Lamp	194.29	
2	Support Rubber "Big" <i>Damaged 17</i>	\$ 250.00	SN X
3	Support Rubber "Small" <i>17</i>	\$ 180.00	SN X
4	Bumper <i>R</i>	\$ 600.00	SN X
	To check all wiring & electrical component for proper function	\$ 40.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 250
	To putty & spray painting & including touch up paint on accident affected areas	\$ 200.00	- 120

Total Parts & Labour of estimate for damaged vehicle

\$ 1,964.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

Mike Aslu

Not Authorised
16/9/21

2-194.30
252

2-145.72
2-390.00

p/p \$535.72
2 days

535.72

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: