

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009707/UUCN2**Date:** 01/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00117912100

Claimant Vehicle No : SLM3721Y **Insured Vehicle No :** SJL7684Z

Date of Loss: 14/09/2021 Nature of Claim: TP Claim No: SNM21D205191/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM3721Y**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZR593355

Reg. Date: 28/03/2017 (Man. Year: 2016) Chassis No: MR053REH104558432

Colour: Red Odometer: 105276 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45ZR17 Rear Tyre Size: 215/45ZR17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,712.65	3,722.37	990.28	21.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	2,070.00	760.00	26.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,542.65	5,792.37	1,750.28	23.21
+ GST 7.00/7.00% (S\$)	527.99	405.47	122.52	23.20
Nett Amount (S\$)	8,070.64	6,197.84	1,872.80	23.21

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: 21/09/2021 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$5792.38

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM3721Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	755.00 FL	*755.00 FL
2	1		*REAR BOOT LOGO	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BOOT COROLLA PLATE	Necessary	48.00 FL	*48.00 FL
4	1		*REAR BOOT ALTIS PLATE	Necessary	48.00 FL	*48.00 FL
5	1		*REAR BOOT LOCK	Twisted	382.00 FL	*382.00 FL
6	1		*REAR BOOT INNER RUBBER	Twisted	185.00 FL	*185.00 FL
7	1		*REAR BOOT CHROME	Not Necessary	233.70 FL	*- FL
8	1		*REAR BOOT LAMP	Not Necessary	395.00 FL	*- FL
9	1		*REAR BUMPER	Distorted	486.50 FL	*486.50 FL
10	2		*REAR BUMPER RETAINER	Bent	221.00 FL	*221.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
13	2		*REAR BUMPER BRACKET	Not Necessary	136.00 FL	*- FL
14	2		*TAIL LAMP	N/s Holder Cracked/O/s Cracked	790.00 FL	*790.00 FL
15	1		*TAIL LAMP LOWER BRACKET	N/s Cracked/O/s Not Necessary	122.00 FL	*61.00 FL
16	1		*REAR END PANEL	Dented	590.00 FL	*590.00 FL
17	1		*REAR END PANEL TOP TRIM	Twisted	240.00 FL	*240.00 FL
18	1		*SPARE TYR BOARD COVER	Not Necessary	267.00 FL	*- FL
19	2		*REAR REVERSE SENSOR	Shorted	580.00 FL	*580.00 FL
20	1		*REAR ANTENNA (BEHIND BUMPER)	Not Necessary	161.00 FL	*- FL
21	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,250.20	4,946.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,537.55	1,224.13
Total Parts (S\$)	4,712.65	3,722.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	TRANSFER REAR BOOT COMPONENTS	New	120.00	60.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY	New	100.00	80.00
4	CAVITY PROTECTION ON AFFECTED AREAS	New	100.00	60.00
5	REMOVE & REFIX REVERSE SENSOR	New	80.00	50.00
6	LABOUR CHARGE	New	1,200.00	800.00
7	SPRAY PAINTING	New	1,200.00	1,000.00
			Gross Labour Cost (\$\$)	2,830.00
				2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >