

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009708/KVCN2**Date:** 03/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00005442101

Claimant Vehicle No : SCY8898G **Insured Vehicle No :** SMK2034C

Date of Loss: 11/09/2021 Nature of Claim: TP Claim No: SNM21D205169/C02/SMK2034C/CHEE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCY8898G**

Make & Model: TOYOTA COROLLA, 1.5 AXIO (M) Engine No: 1NZE922044

Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: NZE1617121969

Colour: Metallic Silver Odometer: 178418 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Dunlop 7 mm Rear Left Side: Habilead 4 mm

Front Right Side: Dunlop 7 mm Rear Right Side: Habilead 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	975.00	548.00	427.00	43.79
Miscellaneous Items	200.00	200.00	0.00	0.00
Labour	1,230.00	1,050.00	180.00	14.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,405.00	1,798.00	607.00	25.24
Approved Total (Overridden) (\$\$)		1,750.00		
(\$\$)	2,405.00	1,750.00	655.00	27.23
+ GST 7.00/7.00% (\$\$)	168.35	122.50	45.85	27.23
Nett Amount (\$\$)	2,573.35	1,872.50	700.85	27.23

INSPECTION

Date of Assignment: 12/11/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 11/11/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
Parts:	143	TOYOTA COROLLA 1.5 AXIO (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY8898G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled/Cracked	210.00 F	*210.00 FL
2	1		*1 PC REAR BOOT	Buckled	290.00 F	*290.00 FL
3	1		*1 PC REAR BOOT INNER LOCK	Repair	60.00 F	*- FL
4	1		*1 PC REAR BOOT INNER RUBBER	Cut	80.00 F	*80.00 FL
5	1		*1 PC REAR BOOT LOGO	Necessary	30.00 F	*30.00 FL
6	1		*1 PC REAR BOOT EMBLEM - COROLLA	Necessary	25.00 F	*25.00 FL
7	1		*1 PC REAR BOOT EMBLEM - AXIO	Necessary	25.00 F	*25.00 FL
8	1		*1 PC REAR BOOT EMBLEM	Necessary	25.00 F	*25.00 FL
9	1		*1 PC REAR END PANEL	Repair	230.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	975.00 685.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 137.00
					Total Parts (\$\$)	975.00 548.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 SET REVERSE SENSOR Shorted	200.00	200.00
Sub Total (\$\$)			200.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR BOOT & ATTACHMENT,KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	New	550.00	450.00
2	PUTTY & RESPRAY ON REAR BOOT,REAR PANEL,REAR BUMPER	New	680.00	600.00
Gross Labour Cost (\$\$)			1,230.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >