

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009710/KTCN2**Date:** 23/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00010732100		
Claimant Vehicle No :	SMW1572J	Insured Vehicle No :	SMX5831E		
Date of Loss:	13/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205227/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1572J	Engine No:	2ARJ123280
Make & Model:	TOYOTA VELLFIRE, 2.4 DBA-ANH20W (A)	Chassis No:	AGH300197416
Reg. Date:	25/04/2019 (Man. Year: 2018)	Odometer:	62730 km
Colour:	Metallic Pearl White		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,207.00	4,734.00	4,473.00	48.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,620.00	1,930.00	54.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,757.00	6,354.00	6,403.00	50.19
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	12,757.00	5,000.00	7,757.00	60.81
+ GST 7.00/7.00% (\$\$)	892.99	350.00	542.99	60.81
Nett Amount (\$\$)	13,649.99	5,350.00	8,299.99	60.81

INSPECTION

Date of Assignment:	19/09/2021		
Date Inspected:	20/09/2021	Inspected At:	176 SIN MING DRIVE, #01-14, SIN MING AUTOCARE SINGAPORE 575721 REPAIRER: GOLD PERFORMANCE
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2021)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 DBA-ANH20W (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW1572J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE/BOOTS	Bent	1,260.00 F	*1,260.00 FL
2	1		*PULLING CAP	Missing	42.00 F	*42.00 FL
3	1		*REAR TAILGATE CHROME PANEL	Serviceable	580.00 F	*- FL
4	1		*REAR VELLFIRE BADGE (SET)	Necessary	75.00 F	*75.00 FL
5	1		*REAR TAILGATE INNER GARNISH (COVER)	Warped/Dented	620.00 F	*620.00 FL
6	1		*REAR TAILGATE RUBBER MOULDING	Dented/Distorted	180.00 F	*180.00 FL
7	1		*REAR WINDSCREEN ASSY	Serviceable	770.00 F	*- FL
8	1		*SET REAR WINDSCREEN GUM/SEALANT	Necessary	44.00 F	*44.00 FL
9	2		*TAILLAMP ASSY	Cut	1,360.00 F	*1,360.00 FL
10	2		*REAR TAILGATE ABSORBER STAND	Serviceable	380.00 F	*- FL
11	1		*REAR BUMPER	Bent/Cracked	1,224.00 F	*1,217.00 FL
12	2		*REAR BUMPER SUPPORT BRACKET	Repair	130.00 F	*- FL
13	2		*REAR BUMPER TOWING HOOK COVER	Missing	44.00 F	*44.00 FL
14	1		*REAR TAILGATE LOCK	Dented	330.00 F	*330.00 FL
15	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Dented (2 Pcs only)	760.00 F	*380.00 FL
16	2		*REAR BUMPER RETAINER BRACKET	Serviceable	170.00 F	*- FL
17	10		*REAR BUMPER CLIPS	Necessary	25.00 F	*25.00 FL
18	2		*RUBBER STOPPER FOR TAILGATE	Serviceable	18.00 F	*- FL
19	1		*REAR PANEL GARNISH	Mtg Distorted	155.00 F	*155.00 FL
20	1		*REAR PANEL	Bent	580.00 F	*580.00 FL
21	2		*REAR TAILLAMP PANEL (CORNER)	Repair	460.00 F	*- FL
					Sub Total (\$\$)	9,207.00 6,312.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,578.00
					Total Parts (\$\$)	9,207.00 4,734.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REPAIR AND RENEW ALL AREAS AFFECTED BY THE ACCIDENT	New	1,600.00	700.00
2	TO SPRAY PAINT ALL AREAS AFFECTED BY THE ACCIDENT	New	1,800.00	800.00
3	TO REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	120.00
Gross Labour Cost (\$)			3,550.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >