

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG121009713/EQF3N2**Date:** 16/12/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBD9137K**Insured Vehicle No :** YP769K

Date of Loss: 06/09/2021

Nature of Claim: TP

Claim No: CDMCG21001765

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBD9137K**

Make &amp; Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V (M)

Engine No: YD25361168A

Reg. Date: 20/07/2015 (Man. Year: 2014)

Chassis No: JN1MC2E26Z0003984

Colour: Grey

Odometer: 80028 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,861.28	1,365.52	495.76	26.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,788.00	2,613.00	1,175.00	31.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,649.28</b>	<b>3,978.52</b>	<b>1,670.76</b>	<b>29.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	395.45	278.50	116.95	29.57
<b>Nett Amount (S\$)</b>	<b>6,044.73</b>	<b>4,257.02</b>	<b>1,787.71</b>	<b>29.57</b>

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 17/09/2021

Inspected At:

Tan Chong Motor Sales Pte Ltd (HQ)

911 BUKIT TIMAH ROAD

Singapore 589623

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Dec 2021)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR EURO V (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD9137K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM-RADIATOR	Not Necessary	79.90 FN	*- FN
2	10		*CLIP	Necessary	13.00 FN	*13.00 FN
3	1		*LAMP ASSY-RH	Broken	441.40 FN	*441.40 FN
4	1		*PANEL-FRONT	Dented	1,227.50 FN	*1,227.50 FN
5	1		*GRILLE-RADIATOR	Not Necessary	527.30 FN	*- FN
6	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,319.10</b>	<b>1,701.90</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	457.82	336.38
<b>Total Parts (\$\$)</b>	<b>1,861.28</b>	<b>1,365.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONDUCT CONSULT,RESET & PROGRAMMING	New	240.00	240.00
2	FOCUS & ADJUST H/LAMP,RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	New	48.00	48.00
3	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	New	240.00	120.00
4	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	100.00
5	REMOVE/INSTALL BLOWER/HEATER UNIT TO FACILITATES REPAIRS & REFILL AIRCON GAS	New	360.00	0.00
6	REMOVE/INSTALL DASHBOARD	New	240.00	240.00
7	REPAIR LH FR PANELCORNER,FR PANEL & FR BUMPER REPAIR FR CENTER PANEL	New	1,560.00	1,365.00
8	S/PAINT FR BUMPER,FR CENTER PANEL,LH CORNER PANEL,FR PANEL	New	1,000.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,788.00</b>	<b>2,613.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >