

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009715/BTF3N2**Date:** 17/11/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001345778
Claimant Vehicle No :	SMJ5073A	Insured Vehicle No :	SDN1601M
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	262718

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ5073A	Engine No:	3A92UHN8607
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001204
Reg. Date:	08/03/2019 (Man. Year: 2018)	Odometer:	258259 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,864.40	5,288.60	3,575.80	40.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	2,640.00	1,030.00	28.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,534.40	7,928.60	4,605.80	36.75
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	12,534.40	5,600.00	6,934.40	55.32
+ GST 7.00/7.00% (S\$)	877.41	392.00	485.41	55.32
Nett Amount (S\$)	13,411.81	5,992.00	7,419.81	55.32

INSPECTION

Date of Assignment:	16/09/2021	
Date Inspected:	17/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	12.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Nov 2021)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ5073A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	828.00 FL	*828.00 FL
2	1		*BOOTLID ATTRAGE EMBLEM	Necessary	38.00 FL	*38.00 FL
3	1		*BOOTLID MIVEC EMBLEM	Necessary	40.00 FL	*40.00 FL
4	1		*BOOTLID CENTRE EMBLEM	Necessary	45.00 FL	*45.00 FL
5	1		*BOOTLID RH HINGE	Not Damaged	192.00 FL	*- FL
6	1		*BOOTLID LH HINGE	Not Damaged	192.00 FL	*- FL
7	1		*BOOTLID LOCK	Jammed	206.00 FL	*139.00 FL
8	1		*BOOTLID LOCK CATCH	Not Damaged	65.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Torn	155.00 FL	*155.00 FL
10	1		*REAR BUMPER	Broken	740.00 FL	*708.00 FL
11	1		*REAR BUMPER RH SIDE RETAINER	Necessary	75.00 FL	*34.50 FL
12	1		*REAR BUMPER LH SIDE RETAINER	Necessary	75.00 FL	*34.50 FL
13	1		*REAR BUMPER RH SIDE HOLDER BRACKET	No such part	36.00 FL	*- FL
14	1		*REAR BUMPER LH SIDE HOLDER BRACKET	No such part	36.00 FL	*- FL
15	1		*REAR BUMPER LOWER SPOILER (ORIGINAL)	Broken	1,643.00 FL	*600.00 FL
16	1		*END PANEL	Dented	421.00 FL	*421.00 FL
17	1		*END PANEL INNER GARNISH	Broken	62.00 FL	*62.00 FL
18	1		*END PANEL INNER AIR DUCT	Broken	30.00 FL	*30.00 FL
19	1		*END PANEL INNER AIR DUCT GARNISH	Broken	40.00 FL	*40.00 FL
20	1		*END PANEL RH SIDE GUIDE GARNISH	Not Damaged	96.00 FL	*- FL
21	1		*END PANEL LH SIDE GUIDE GARNISH	Missing	96.00 FL	*96.00 FL
22	1		*END PANEL BUZZER SENSOR	Broken	90.00 FL	*90.00 FL
23	1		*END PANEL ANTENNA SENSOR	Broken	95.00 FL	*95.00 FL
24	1		*FLOOR PANEL TOP COVER BOARD	Broken	335.00 FL	*195.00 FL
25	1		*FLOOR PANEL	Not Damaged	906.00 FL	*- FL
26	1		*RH TAILLAMP ASSY	Broken	332.00 FL	*332.00 FL
27	1		*LH TAILLAMP ASSY	Broken	332.00 FL	*332.00 FL
28	1		*REAR LH FENDER	Dented	723.00 FL	*723.00 FL
29	1		*REAR LH FENDER INNER TRIM	Torn	158.00 FL	*158.00 FL
30	1		*REAR RH FENDER INNER TRIM	Torn	158.00 FL	*158.00 FL
31	1		*EXHAUST SILENCER	Not Damaged	576.00 FL	*- FL
32	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
33	1		*REAR WINDSCREEN GLASS INNER SEAL	Bent	50.00 FS	*30.00 FS
34	1		*BOOTLID C&C EMBLEM	Necessary	60.00 FS	*60.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
36	1		*REAR BUMPER REVERSE SENSOR (SET)	Short Circuit	280.00 FS	*200.00 FS
37	1		*SET REAR FENDER RH INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
38	1		*SET REAR FENDER LH INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
39	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
40	1		*FLOOR PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS
41	1		*REAR LH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
42	1		*REAR NUMBER PLATE	Not Damaged	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,746.00	5,824.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	881.60	535.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (\$\$)					8,864.40	5,288.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,600.00	1,400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	1,000.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	200.00	60.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND RUBBER HANGERS TO ASSIST REPAIR	New	100.00	0.00
9	REMOVE AND REINSTALL BOOTLID REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
Gross Labour Cost (\$)			3,670.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >