

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009722/UGA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900089684
Claimant Vehicle No :	SGV9079R	Insured Vehicle No :	SKL4704H
Date of Loss:	14/09/2021	Nature of Claim:	TP
		Claim No:	6830671153SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV9079R	Engine No:	HR15141916A
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0004832
Reg. Date:	28/06/2007 (Man. Year: 2007)	Odometer:	138167 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,981.32	619.83	8,361.49	93.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,140.00	2,290.00	66.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,411.32	1,759.83	10,651.49	85.82
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	12,411.32	1,400.00	11,011.32	88.72
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
		(S\$)	1,900.00	
Liabe Amount (50.00%) (S\$)		950.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		957.45		
Global Sum Settlement (S\$)		900.00		

INSPECTION

Date of Assignment:	16/09/2021		
Date Inspected:	16/09/2021	Inspected At:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt Singapore 428586
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented / Deformed	556.90 FL	*556.90 FL
2	1		*REAR BOOTLID ASSY	Not Necessary	922.60 FL	*- FL
3	1		*REAR END LOWER PANEL ASSY	Repair	486.60 FL	*- FL
4	1		*REAR LEFT FENDER	Not Necessary	768.30 FL	*- FL
5	1		*REAR RIGHT FENDER	Not Necessary	768.30 FL	*- FL
6	1		*REAR SPARE TYRE FLOOR PANEL	Not Necessary	948.40 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	86.40 FN	*- FN
8	2		*REAR BUMPER BRACKET	Not Necessary	84.30 FN	*- FN
9	1		*REAR BUMPER INNER SPONGE	Not Necessary	128.60 FN	*- FN
10	1		*REAR BOOTLID LOCK	Not Necessary	106.90 FN	*- FN
11	1		*REAR BOOTLID LOCK CATCH	Not Necessary	62.60 FN	*- FN
12	1		*REAR BOOTLID SWITCH	Not Necessary	176.80 FN	*- FN
13	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	188.70 FN	*- FN
14	1		*REAR BOOTLID CENTRE LOGO	Not Necessary	48.20 FN	*- FN
15	1		*REAR BOOTLID LATIO EMBLEM	Not Necessary	46.30 FN	*- FN
16	1		*REAR BOOTLID OUTER CHROME MOULDING	Not Necessary	117.60 FN	*- FN
17	2		*REAR BOOTLID HINGES	Not Necessary	86.30 FN	*- FN
18	2		*REAR BOOTLID NO PLATE LAMP	Not Necessary	103.10 FN	*- FN
19	2		*REAR BOOTLID RUBBER STOPPER	Not Necessary	36.80 FN	*- FN
20	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	278.80 FN	*- FN
21	1		*REAR LEFT TAILLAMP	Not Necessary	476.40 FN	*- FN
22	1		*REAR RIGHT TAILLAMP	Not Necessary	476.40 FN	*- FN
23	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	959.40 FN	*- FN
24	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	36.60 FN	*- FN
25	1		*REAR END LOWER PANEL TOP GARNISH	Not Necessary	116.20 FN	*- FN
26	1		*REAR LEFT FENDER COWLING	Not Necessary	102.80 FN	*- FN
27	1		*REAR RIGHT FENDER COWLING	Not Necessary	102.80 FN	*- FN
28	1		*REAR LEFT FENDER INNER SIDE GARNISH	Not Necessary	286.40 FN	*- FN
29	1		*REAR RIGHT FENDER INNER SIDE GARNISH	Not Necessary	286.40 FN	*- FN
30	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	288.50 FN	*- FN
31	1		*REAR SPARE TYRE TOP COVER	Not Necessary	177.60 FN	*- FN
32	1		*REAR SPARE TYRE TOP LOCK HOLDER	Not Necessary	78.60 FN	*- FN
33	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
34	4		*REAR BOOTLID OUTER CHROME MOULDING CLIPS	Not Necessary	40.00 FS	*- FS
35	8		*REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
36	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
38	4		*REAR LEFT FENDER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
39	4		*REAR RIGHT FENDER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
40	6		*REAR LEFT FENDER INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
41	6		*REAR RIGHT FENDER INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
42	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
43	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
44	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
45	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
46	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
47	1		*REAR SPARE TYRE FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
48	1		*REAR SPARE TYRE FLOOR PANEL INSULATOR PAD	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	10,810.60	786.90
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,335.33	167.07
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	493.95	0.00
Total Parts (\$\$)	8,981.32	619.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS INCLUDING FLOOR PANEL	New	1,200.00	580.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	480.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	0.00
6	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	0.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	0.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	0.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
11	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,430.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >