

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009724/VEA3Q2
Date: 20/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070092749-01
Claimant Vehicle No :	SHB8098K	Insured Vehicle No :	GBH4984T
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	6349150579SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8098K	Engine No:	D4FBGZ115768
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Chassis No:	TMAD281UVHJ125072
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	383546 km
Colour:	Silver		
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	796.89	98.00	698.89	87.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	360.00	140.00	28.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,296.89	458.00	838.89	64.68
+ GST 7.00/7.00% (S\$)	90.78	32.06	58.72	64.68

Nett Amount (S\$)	1,387.67	490.06	897.61	64.68
<hr/>				
+ Loss of Use (2.5 x S\$40.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$62.06/day) (S\$)		155.15		
+ Doc/Search Fee (S\$)		7.45		
		<hr/>		
Nett Liability (S\$)		752.66		
		<hr/>		
Global Sum Settlement (S\$)		750.00		
		<hr/>		

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 20/09/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
3	1		*FRONT NUMBER PLATE & HOLDER	Cracked	50.00 FS	*50.00 FS
4	1		*SUNDRY	Serviceable	50.00 FS	*- FS
					Sub Total (\$)	959.11 98.00
					- List Item Discount on L Items 20.00/20.00% (\$)	162.22 0.00
					Total Parts (\$)	796.89 98.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN,REPAIR RESHAPE OF THE SAME ETC	New	250.00	180.00
2	TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER	New	250.00	180.00
Gross Labour Cost (\$\$)			500.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >