

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009727/AGA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900107883
<b>Claimant Vehicle No :</b>	GBC2730Z	<b>Insured Vehicle No :</b>	SML9077C
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	0838364052SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC2730Z</b>	Engine No:	HIDDEN
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y00K201744
Reg. Date:	01/10/2011 (Man. Year: 2011)	Odometer:	363635 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,305.37	917.87	1,387.50	60.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	630.00	920.00	59.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,855.37</b>	<b>1,547.87</b>	<b>2,307.50</b>	<b>59.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	3,855.37	1,200.00	2,655.37	68.87
<b>+ GST 7.00/7.00% (S\$)</b>	269.88	84.00	185.88	68.88
<b>Nett Amount (S\$)</b>	<b>4,125.25</b>	<b>1,284.00</b>	<b>2,841.25</b>	<b>68.87</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		43.90		
<b>Nett Liability (S\$)</b>		<b>1,727.90</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,700.00</b>		

INSPECTION

Date of Assignment:	17/09/2021	
Date Inspected:	20/09/2021	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE 70KM/H STICKER	Necessary	20.00 FS	*15.00 FS
2	1		*REAR TAIL GATE O/S STOPPER BRACKET	Repair	110.00 FL	*- FL
3	1		*REAR O/S TAIL LAMP	Cracked	270.50 FL	*270.50 FL
4	1		*REAR FIBER GLASS	Cracked	2,000.00 FS	*700.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (\$)</b>	<b>2,400.50</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>95.13</b>
					<b>Total Parts (\$)</b>	<b>2,305.37</b>

985.50  
67.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE REAR DAMAGE PARTS	New	800.00	200.00
2	TO SPRAY PAINTING	New	700.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,550.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >