

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21009728/KTF3N2**Date:** 27/10/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHD9762J	Insured Vehicle No :	SLX3657S
Date of Loss:	14/09/2021	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9762J	Engine No:	2ZR2H07865
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU003092403
Reg. Date:	30/10/2020 (Man. Year: 2020)	Odometer:	99735 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,300.32	9,572.25	9,728.07	50.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,460.00	2,640.00	51.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,400.32	12,032.25	12,368.07	50.69
+ GST 7.00/7.00% (S\$)	1,708.02	842.26	865.76	50.69
Nett Amount (S\$)	26,108.34	12,874.51	13,233.83	50.69

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	15/09/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9762J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER,FRONT BUMPER	Bent	521.00 FL	*521.00 FL
2	1	*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Bent	716.60 FL	*716.60 FL
3	1	*REINFORCEMENT,FRONT BUMPER NO 2	Repair	246.10 FL	*- FL
4	1	*ABSORBER,FRONT BUMPER LOWER	Cracked	132.70 FL	*132.70 FL
5	1	*ABSORBER,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
6	1	*EXTENSION,FRONT BUMPER,LH	Serviceable	120.10 FL	*- FL
7	1	*MOULDING,FRONT BUMPER SIDE,LH	Cracked	95.60 FL	*95.60 FL
8	1	*BRACKET,FRONT BUMPER SIDE,LH	Distorted	59.30 FL	*59.30 FL
9	1	*JAR ASSY,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
10	1	*UNIT ASSY,HEADLAMP LH	Cracked	2,637.60 FL	*2,637.60 FL
11	1	*COMPUTER SUB-ASSY,HEADLAMP,LH NO 1	Serviceable	3,772.50 FL	*- FL
12	1	*LAMP ASSY,FOG,LH	Serviceable	237.10 FL	*- FL
13	1	*GRILLE SUB-ASSY,RADIATOR	Serviceable	422.50 FL	*- FL
14	1	*GRILLE RADIATOR,LOWER NO 1	Cut	178.60 FL	*178.60 FL
15	1	*EMBLEM ASSY,RADIATOR GRILLE	Necessary	105.80 FL	*105.80 FL
16	1	*COVER SUB-ASSY,FRONT PILLAR,UPR LH	Serviceable	100.40 FL	*- FL
17	1	*BRACE SUB-ASSY,DASH TO FRAME,LH	Repair	182.20 FL	*- FL
18	1	*FENDER SUB-ASSY,FRONT LH	Bent	977.80 FL	*977.80 FL
19	1	*LINER,FRONT FENDER,LH	Cracked	210.30 FL	*210.30 FL
20	1	*EMBLEM,SIDE PANEL,LH	Necessary	54.60 FL	*54.60 FL
21	1	*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	*977.80 FL
22	1	*LINER,FRONT FENDER,RH	Serviceable	202.50 FL	*- FL
23	1	*EMBLEM,SIDE PANEL,RH	Necessary	54.60 FL	*54.60 FL
24	1	*PANEL SUB-ASSY,FRONT DOOR,RH	Bent	1,300.70 FL	*1,300.70 FL
25	1	*LOCK ASSY,FRONT DOOR W/MOTOR,RH	Repair	603.20 FL	*- FL
26	1	*MOULDING,FRONT DOOR WINDOW FRAME,FRONT RH	Serviceable	38.60 FL	*- FL
27	1	*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	*- FL
28	1	*HANDLE ASSY,FRONT DOOR,OUTSIDE RH	Dented	390.60 FL	*390.60 FL
29	1	*MOTOR ASSY,POWER WINDOW REGULATOR RH	Serviceable	926.00 FL	*- FL
30	1	*WEATHERSTRIP,FRONT DOOR OPENING TRIM,RH	Serviceable	321.10 FL	*- FL
31	1	*HINGE ASSY,FRONT DOOR,LOWER RH	Repair	110.60 FL	*- FL
32	1	*HINGE ASSY,FRONT DOOR,UPPER RH	Repair	97.50 FL	*- FL
33	1	*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH	Serviceable	238.30 FL	*- FL
34	1	*TAPE,BLACK OUT,NO 2 FRT RH	Necessary	43.50 FL	*43.50 FL
35	1	*TAPE,BLACK OUT,NO 1 FRT RH	Necessary	13.30 FL	*13.30 FL
36	1	*TAPE,BLACK OUT,NO 3 FRT RH	Necessary	26.30 FL	*26.30 FL
37	1	*PANEL SUB-ASSY,REAR DOOR RH	Bent	1,294.90 FL	*1,294.90 FL
38	1	*FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE RH	Serviceable	193.50 FL	*- FL
39	1	*HANDLE ASSY,REAR DOOR OUTSIDE RH	Serviceable	97.40 FL	*- FL
40	1	*WEATHERSTRIP,REAR DOOR OPENING TRIM,RH	Serviceable	293.00 FL	*- FL
41	1	*REGULATOR SUB-ASSY,REAR DOOR WINDOW,RH	Serviceable	206.70 FL	*- FL
42	1	*TAPE,BLACK OUT,NO 2 REAR RH	Necessary	34.90 FL	*34.90 FL
43	1	*TAPE,BLACK OUT,NO 3 REAR RH	Necessary	15.40 FL	*15.40 FL
44	1	*TAPE,BLACK OUT,NO 1 REAR RH	Necessary	21.90 FL	*21.90 FL
45	1	*HINGE ASSY,REAR DOOR LOWER RH	Repair	87.10 FL	*- FL
46	1	*HINGE ASSY,REAR DOOR UPPER RH	Repair	98.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
47	1	*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	*- FL
48	1	*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	*- FL
49	1	*MOULDING ASSY,BODY ROCKER PANEL RH	Serviceable	594.80 FL	*- FL
50	1	*FRT FENDER LINER CLIP (2 Pcs)	Necessary (1 Pc only)	130.00 FS	*65.00 FS
51	1	*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
52	1	*FRT BUMPER CLIP	Necessary	75.00 FS	*50.00 FS
53	1	*HUB CAP	Serviceable	211.50 FS	*- FS
54	1	*RIM	Dented	1,879.40 FS	*1,879.40 FS
55	1	*SET CLIP,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS
56	2	*DOOR STICKER TRANSCAB	Necessary	200.00 FS	*120.00 FS
57	1	*DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
58	2	*SET DOOR TRIM CLIP	Not Necessary	140.00 FS	*- FS
59	2	*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
60	1	*COVER SUB-ASSY,ENGINE UNDER,NO 2	Serviceable	241.90 FL	*- FL
61	1	*MOTOR ASSY,POWER WINDOW REGULATOR,REAR RH	Serviceable	926.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,731.80	12,038.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,431.48	2,465.95
Total Parts (\$\$)	19,300.32	9,572.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	120.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	700.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,540.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >