

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 477A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE & HOLDER (SN)	BROKEN	60.00	60.00
1	BUMPER COVER FRT EVO (SN)	BROKEN	2,081.20	1,873.08
1	BUMPER BEAM FRT EVOQ (SN)	BENT	1,119.70	1,007.73
1	BUMPER BRACKET FRT C (SN)	BROKEN	506.80	456.12
			3,767.70	3,396.93
	<u>LABOUR</u>			
	TO REPLACE FRT BUMPER, BUMPER BEAM, ETC.		2,000.00	1,300.00
	TO SPRAYPAINT ON FRT BUMPER.		1,800.00	1,000.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
			4,421.00	2,921.00
	GRAND TOTAL		8,188.70	6,317.93

RECOMMENDED COST OF REPAIRS		6,317.93
LESS EXCESS		-2,500.00
NETT LIABILITY		3,817.93

Report Ref No. CS/AWA21009732/Eqf3e2

CHEN TSUE YEE

**Automotive Assessor** 

X:2.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.