



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7500J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH BALANCER	SCRATCHED	156.00	81.00
1	FRONT BRAKE LEVEL	SCRATCHED	143.00	70.00
1	REAR TAIL MUDFLAT	CUT	273.00	65.00
1	REAR TAIL LAMP	CRACKED	364.00	295.00
1	REAR TAIL FENDER	CUT	318.50	85.00
1	REAR EXHAUST PIPE	SCRATCHED	3,120.00	136.00
2	REAR LH & RH SIDE LAMP	CRACKED	156.00	120.00
	LESS 10% DISCOUNT		-453.05	-85.20
			4,077.45	766.80
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	25.00	15.00
			25.00	15.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS.		540.00	150.00
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS.		72.00	30.00
	TRANSPORT MOTORCYCLE TO WORKSHOP FOR REPAIRS.		72.00	30.00
			684.00	210.00
	GRAND TOTAL		4,786.45	991.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00

Report Ref No. CS3/SMR21008231/Vuf3e2-1

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.