

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009734/UTCE2

Date: 05/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00001752100
Claimant Vehicle No: GBE2362S Insured Vehicle No: GV5477B
Date of Loss: 14/09/2021 Nature of Claim: TP Claim No: SNM21D205255/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE2362S
Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M) Engine No: 263A50007396767
Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: ZFA26300006A82304
Colour: Silver Odometer: 120547 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Grenlander 6 mm Rear Left Side: Gaenlander 6 mm
Front Right Side: Grenlander 6 mm Rear Right Side: Gaenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,970.00	3,675.00	1,295.00	26.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,037.27	1,173.37	863.90	42.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,007.27	4,848.37	2,158.90	30.81
+ GST 7.00/7.00% (S\$)	490.51	339.39	151.12	30.81
Nett Amount (S\$)	7,497.78	5,187.76	2,310.02	30.81

INSPECTION

Date of Assignment: 17/09/2021 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 17/09/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 6.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2021)		
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE2362S)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*total parts		4,425.00 F	*3,455.00 F
2	1	REVERSE SENSOR	*total Extra		280.00 F	*- F
Supplementary #1						
3	1		*HEADLAMP TOP PANEL RH	Distorted	150.00 F	*105.00 F
4	1		*SIDE PANEL RH	Distorted	55.00 F	*55.00 F
5	1		*BUMPER GRILLE	Distorted	60.00 F	*60.00 F
F=Franchise part.						
Total Parts (S\$)					4,970.00	3,675.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Labour	New	777.00	245.70
2	Total paint	New	1,260.27	927.67
Gross Labour Cost (S\$)			2,037.27	1,173.37

Report was unsubmitted during this print-out.

< END OF ESTIMATES >