

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009739/AGS3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800048539-03
Claimant Vehicle No :	SMY2730C	Insured Vehicle No :	GBE9567Y
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	6337382325SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY2730C	Engine No:	R16B11002021
Make & Model:	HONDA CIVIC, 1.6 VTI-S (A)	Chassis No:	JHMFB1630CS201518
Reg. Date:	10/06/2013 (Man. Year: 2012)	Odometer:	185424 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,449.60	5,021.60	7,428.00	59.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,750.00	3,350.00	65.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,549.60	6,771.60	10,778.00	61.41
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	17,549.60	5,400.00	12,149.60	69.23
+ GST 7.00/7.00% (S\$)	1,228.47	378.00	850.47	69.23
Nett Amount (S\$)	18,778.07	5,778.00	13,000.07	69.23
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,614.45		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	20/09/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	O/S Smashed	1,692.80 FL	*846.40 FL
2	1		*HEADLAMP LOWER BRACKET RH	Bent	39.20 FL	*39.20 FL
3	1		*FRONT GRILLE	Cracked	273.90 FL	*273.90 FL
4	2		*FRONT GRILLE CENTER SUPPORT BRACKET	Not Necessary	73.00 FL	*- FL
5	1		*FRONT GRILLE LOGO	Necessary	39.40 FL	*39.40 FL
6	1		*FRONT GRILLE CHROME	Not Necessary	262.80 FL	*- FL
7	1		*FRONT BUMPER	Distorted	683.80 FL	*683.80 FL
8	1		*FRONT BUMPER BOTTOM GARNISH	Not Necessary	125.60 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Cracked	194.60 FL	*194.60 FL
10	1		*FRONT BUMPER SIDE COVER RH	Missing	85.30 FL	*85.30 FL
11	1		*FRONT BUMPER SIDE BOTTOM GARNISH RH	Not Necessary	120.30 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Dented	384.80 FL	*384.80 FL
13	1		*FRONT BUMPER RETAINER	O/S Damaged	64.40 FL	*32.20 FL
14	1		*FRONT FENDER RH	Distorted	577.50 FL	*577.50 FL
15	1		*FRONT FENDER SUPPORT BRACKET RH	Not Necessary	42.60 FL	*- FL
16	1		*FRONT FENDER INNER COWLING RH	Cut	142.80 FL	*142.80 FL
17	1		*FRONT WHEEL RIM RH	Not Necessary	984.70 FL	*- FL
18	1		*FRONT SHOCK ABSORBER RH	Not Necessary	389.40 FL	*- FL
19	1		*FRONT LOWER ARM RH	Not Necessary	397.80 FL	*- FL
20	1		*FRONT KNUCKLE ARM RH	Not Necessary	342.10 FL	*- FL
21	1		*FRONT KNUCKLE ARM INNER BEARING RH	Not Necessary	176.40 FL	*- FL
22	1		*FRONT WHEEL HUP RH	Not Necessary	199.20 FL	*- FL
23	1		*WASHER TANK	Cut	168.40 FL	*168.40 FL
24	1		*FRONT SUPPORT PANEL	Buckled	478.30 FL	*478.30 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	183.10 FL	*- FL
26	1		*AIR CON CONDENSER	Not Necessary	899.40 FL	*- FL
27	4		*AIR CON CONDENSER MOUNTING	Not Necessary	48.00 FL	*- FL
28	2		*AIR CON CONDENSOR TOP BRACKET	Not Necessary	50.00 FL	*- FL
29	1		*AIR CON FAN BLADE	Not Necessary	98.90 FL	*- FL
30	1		*AIR CON FAN MOTOR	Not Necessary	498.20 FL	*- FL
31	1		*AIR CON FAN COWLING	Not Necessary	189.70 FL	*- FL
32	1		*AIR CON FAN COWLING (SUCTION)	Not Necessary	129.60 FL	*- FL
33	1		*AIR CON PIPE (PRESSURE)	Not Necessary	299.90 FL	*- FL
34	1		*RADIATOR	Not Necessary	1,507.40 FL	*- FL
35	1		*RADIATOR SIDE GARNISH	O/S Deformed	90.00 FL	*45.00 FL
36	2		*RADIATOR TOP BRACKET	Not Necessary	64.00 FL	*- FL
37	4		*RADIATOR MOUNTING	Not Necessary	48.00 FL	*- FL
38	1		*RADIATOR SPARE TANK	Not Necessary	93.80 FL	*- FL
39	1		*ABS PUMP	Cracked	1,897.90 FL	*1,897.90 FL
40	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*SET FRONT BUMPER SIDE BOTTOM GARNISH CLIP	Not Necessary	50.00 FS	*- FS
42	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
43	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*SET RADIATOR SIDE GARNISH LH CLIP	Necessary	30.00 FS	*10.00 FS
45	1		*FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
46	1		*FRONT FENDER INNER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
47	1		*SET FRONT FENDER INNER GARNISH CLIP LH	Not Necessary	50.00 FS	*- FS
48	1		*SET FRONT PARKING SENSOR	Damaged	220.00 FS	*220.00 FS
49	1		*FRONT WHEEL TYRE RH	Not Necessary	380.00 FS	*- FS
50	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
51	1		*POWER STEERING OIL	Not Necessary	60.00 FS	*- FS
52	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,257.00** **6,199.50**
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,807.40 1,177.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	12,449.60	5,021.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND PRESSURE TEST	New	80.00	60.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
8	TO PRESS FRONT WHEEL BEARING	New	60.00	0.00
9	FOUR WHEEL ALIGNMENT	New	120.00	0.00
10	RESET ABS LIGHT	New	350.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (S\$)	5,100.00
				1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >