

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009740/BUCE2

Date: 20/10/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00081362000		
Claimant Vehicle No :	SJR3285L	Insured Vehicle No :	GBG6234S		
Date of Loss:	15/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205257/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR3285L	Engine No:	4GR0562501
Make & Model:	TOYOTA LEXUS, 2.5 IS250 (A)	Chassis No:	JTHBK262205098960
Reg. Date:	19/06/2009 (Man. Year: 2009)	Odometer:	207511 km
Colour:	Grey		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	265/30 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,458.09	5,973.04	8,485.05	58.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,520.00	1,400.00	47.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,378.09	7,493.04	9,885.05	56.88
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	17,378.09	6,000.00	11,378.09	65.47
+ GST 7.00/7.00% (S\$)	1,216.47	420.00	796.47	65.47
Nett Amount (S\$)	18,594.56	6,420.00	12,174.56	65.47

INSPECTION

Date of Assignment:	17/09/2021	
Date Inspected:	20/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	143	TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR3285L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,631.00 FL	*739.10 FL
2	1		*FRONT BUMPER	Broken	835.00 FL	*541.00 FL
3	1		*FRONT BUMPER CENTRE UPPER RUBBER SEAL	Not Damaged	64.00 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP	Broken	322.00 FL	*224.60 FL
5	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	34.00 FL	*34.00 FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
7	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	581.00 FL	*399.00 FL
9	1		*FRONT BUMPER INNER SPONGE	Broken	184.00 FL	*111.80 FL
10	1		*FRONT BUMPER LOWER COVER	Not Damaged	321.00 FL	*- FL
11	1		*RH HEADLAMP ASSY	Broken	1,150.00 FL	*785.30 FL
12	1		*SUPPORT PANEL	Dented	1,017.00 FL	*728.10 FL
13	1		*FRONT GRILLE	Broken	571.00 FL	*226.20 FL
14	1		*FRONT GRILLE EMBLEM	Necessary	86.00 FL	*65.45 FL
15	1		*WIPER WASHER TANK	Not Damaged	208.00 FL	*- FL
16	1		*WIPER WASHER TANK MOTOR	Not Damaged	115.00 FL	*- FL
17	1		*FRONT RH FENDER	Bent	1,433.00 FL	*712.90 FL
18	1		*FRONT RH FENDER SPLASH SHIELD	Torn	329.00 FL	*171.20 FL
19	1		*FRONT RH WHEEL BEARING	Not Damaged	654.00 FL	*- FL
20	1		*FRONT RH LOWER ARM	Not Damaged	759.00 FL	*- FL
21	1		*FRONT RH KNUCKLE ARM	Not Damaged	483.00 FL	*- FL
22	1		*FRONT RH SHOCK ABSORBER	Not Damaged	819.00 FL	*- FL
23	1		*SET BONNET INNER INSULATOR CLIPS	Not Necessary	70.00 FS	*- FS
24	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
25	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*FRONT RH SPORT RIM	Not Damaged	1,050.00 FS	*- FS
27	1		*FRONT RH TYRE	Not Damaged	380.00 FS	*- FS
28	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
29	1		*AIRCON CONDENSER	Bent	1,218.10 FL	*890.10 FL
30	1		*LH HEADLAMP ASSY	Broken	1,150.00 FL	*785.30 FL
31	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,870.10	6,630.05
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,412.01	657.01
Total Parts (\$\$)	14,458.09	5,973.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	60.00	0.00
5	REMOVE AND REINSTALL AIRCON CONDENSER, PIPES AND HOSES TO ASSIST REPAIR. TO REFILL AIRCON GAS	New	200.00	120.00
6	REMOVE AND REINSTALL RADIATOR ASSY, HOSES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT	New	200.00	0.00
7	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
8	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	280.00	0.00
Gross Labour Cost (\$\$)			2,920.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >