

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009743/BUCE2

Date: 18/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049562100
Claimant Vehicle No: SMX1021C Insured Vehicle No: GBE6269C
Date of Loss: 15/09/2021 Nature of Claim: TP Claim No: SNM21D205261/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMX1021C
Make & Model: MERCEDES-BENZ B180 BLUE EFFICIENCY, 1.6 (A) Engine No: 27491030019559
Reg. Date: 04/01/2013 (Man. Year: 2012) Chassis No: WDD2040312A779665
Colour: Brown Odometer: 120689 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,644.18	4,175.12	7,469.06	64.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,300.00	3,030.00	69.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,974.18	5,475.12	10,499.06	65.73
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	15,974.18	4,350.00	11,624.18	72.77
+ GST 7.00/7.00% (S\$)	1,118.19	304.50	813.69	72.77
Nett Amount (S\$)	17,092.37	4,654.50	12,437.87	72.77

INSPECTION

Date of Assignment: 28/09/2021
Date Inspected: 17/09/2021 Inspected At: Team Autopro Pte Ltd - Sin Ming (HQ)
160 Sin Ming Dr
#01-14 Sin Ming Auto City
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2021)

Parts: 143 MERCEDES-BENZ B180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX1021C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	1,402.50 FL	*1,224.00 FL
2	2	*FRONT BUMPER SIDE RETAINER	Necessary	172.60 FL	*136.00 FL
3	1	*FRONT BUMPER SIDE BRACKET	No such part	68.90 FL	*- FL
4	1	*FRONT BUMPER FOG LAMP RH	Crushed	483.90 FL	*290.00 FL
5	1	*FRONT BUMPER FOG LAMP GARNISH RH	Broken	297.60 FL	*142.00 FL
6	1	*FRONT BUMPER CHROME MOULDING SIDE	Broken	185.30 FL	*185.30 FL
7	1	*FRONT FENDER RH	Repair	856.30 FL	*- FL
8	1	*FRONT FENDER RH INNER SHIELD FRONT	Torn	185.30 FL	*185.30 FL
9	1	*FRONT FENDER RH INNER SHIELD REAR	Not Damaged	198.70 FL	*- FL
10	1	*FRONT FENDER CHROME MOULDING RH	Not Necessary	174.00 FL	*- FL
11	1	*HEADLAMP RH	Broken	1,145.60 FL	*1,145.60 FL
12	1	*HEADLAMP LOWER BRACKET RH	Not Damaged	230.00 FL	*- FL
13	1	*FRONT KNUCKLE ARM RH	Not Damaged	843.00 FL	*- FL
14	1	*FRONT KNUCKLE ARM BEARING RH	Jammed	543.00 FL	*285.60 FL
15	1	*FRONT SHOCK ABSORBER RH	Not Damaged	685.90 FL	*- FL
16	1	*FRONT UPPER ARM RH	Dented	423.00 FL	*423.00 FL
17	1	*FRONT TRUST ARM RH	Not Necessary	410.00 FL	*- FL
18	1	*FRONT LOWER ARM RH	No such part	472.00 FL	*- FL
19	1	*KEYLESS CONTROL SWITCH ON/OFF	Not Consistent With The Impact	1,882.60 FL	*- FL
20	1	*SUNDRIES	Not Necessary	80.00 FS	*- FS
21	1	*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1	*FRONT BUMPER FOG LAMP GARNISH CLIPS	No such part	60.00 FS	*- FS
23	1	*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
24	1	*FRONT FENDER INNER SHIELD FRONT CLIPS	Necessary	60.00 FS	*30.00 FS
25	1	*FRONT FENDER INNER SHIELD REAR CLIPS	Not Necessary	60.00 FS	*- FS
26	1	*FRONT ALLOY RIM	Cut	1,150.00 FS	*500.00 FS
27	1	*FRONT TYRE	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,710.20	4,576.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,066.02	401.68
Total Parts (\$\$)	11,644.18	4,175.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT UNDERCARRIAGE	New	450.00	120.00
2	R&R FRONT TYRE & BALANCING	New	100.00	0.00
3	WHEEL ALIGNMENT	New	180.00	60.00
4	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
5	PROGRAMING KEYLESS CONTROL MODULE	New	300.00	0.00
6	CHECK WIRING	New	100.00	0.00
7	UPHOLSTERY	New	300.00	0.00
8	PANEL BEATING	New	1,200.00	600.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (\$\$)			4,330.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >