

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009744/GTCN2**Date:** 28/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00006822001
Claimant Vehicle No :	PA6953R	Insured Vehicle No :	SMM6957C
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205260/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA6953R	Engine No:	2KD1606282
Make & Model:	TOYOTA HIACE, 2.5 (A)	Chassis No:	KDH2220030032
Reg. Date:	22/06/2007 (Man. Year: 2007)	Odometer:	913970 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R16	Rear Tyre Size:	195/65R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,018.92	2,838.06	4,180.86	59.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,170.00	2,230.00	65.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,418.92	4,008.06	6,410.86	61.53
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	10,418.92	3,200.00	7,218.92	69.29
+ GST 7.00/7.00% (\$\$)	729.32	224.00	505.32	69.29
Nett Amount (\$\$)	11,148.24	3,424.00	7,724.24	69.29

INSPECTION

Date of Assignment:	20/09/2021		
Date Inspected:	22/09/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Feb 2022)	
Parts:	N/A	TOYOTA HIACE 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA6953R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	516.70 FL	*516.70 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	178.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	450.00 FL	*380.40 FL
4	1		*FRONT BUMPER SIDE GRILLE LH	Cracked	75.20 FL	*75.20 FL
5	2		*FRONT BUMPER SIDE RETAINER	Cracked	320.60 FL	*60.10 FL
6	1		*HEADLAMP LH	Cracked	670.80 FL	*670.80 FL
7	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	49.60 FL	*- FL
8	1		*FRONT CORNER PANEL LH	Not Necessary	363.70 FL	*- FL
9	1		*FRONT CENTER BEAM	Not Necessary	176.90 FL	*- FL
10	1		*FRONT CENTRE GRILLE	Broken	538.10 FL	*538.10 FL
11	1		*FRONT WIRE SOCKET HOLDER LH	Not Necessary	45.10 FL	*- FL
12	1		*FRONT RADIATOR (SIDE)	Bent	1,063.50 FL	*1,063.50 FL
13	1		*RADIATOR SUPPORT PANEL	Repair	796.20 FL	*- FL
14	1		*BONNET	Repair	1,135.40 FL	*- FL
15	1		*BONNET LOGO	Necessary	80.10 FL	*60.70 FL
16	1		*HORN	Not Necessary	130.00 FL	*- FL
17	1		*WASHER TANK	Cut	197.20 FL	*85.00 FL
18	1		*FRONT DOOR PILLAR (OUTER) LH	Repair	987.60 FL	*- FL
19	1		*FRONT DOOR STEP PANEL GARNISH LH	Broken	409.80 FL	*80.25 FL
			(2 Pcs)			
20	1		*FRONT DOOR STEP PANEL (OUTER) LH	Not Necessary	267.20 FL	*- FL
21	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
22	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*20.00 FS
23	1		*SET FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	80.00 FS	*- FS
24	1		*SET FRONT CENTRE GRILLE CLIP	Necessary	80.00 FS	*20.00 FS
25	1		*SET FRONT DOOR STEP PANEL GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
26	1		*COOLANT	Necessary	50.00 FS	*30.00 FS
27	1		*SET HEADLAMP RING	Cracked	250.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,131.90	3,720.75
- List Item Discount on L Items 25.00/25.00% (\$)	2,112.98	882.69
Total Parts (\$)	7,018.92	2,838.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,200.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	700.00
3	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
4	TUFF COAT	New	250.00	0.00
5	WIRING,BULB CHECKING	New	180.00	30.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	40.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,400.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >