

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009746/KVCN2**Date:** 24/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00040582100	
Claimant Vehicle No :	SFP3088Y	Insured Vehicle No :	SLZ5186K	
Date of Loss:	16/09/2021	Nature of Claim:	TP	Claim No: SNM21D205239/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFP3088Y	Engine No:	LEB7102770
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP72001985
Reg. Date:	08/03/2019 (Man. Year: 2018)	Odometer:	88102 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,431.03	1,976.30	1,454.73	42.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,790.00	560.00	23.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	5,781.03	3,766.30	2,014.73	34.85

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	20/09/2021	Inspected At:	Ngs Automotive (HQ) BLK 10 AMK IND PK 2A #02-01 Singapore 568047
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Sep 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFP3088Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH (NPA)	Repair	0.00 FL	*- FL
2	1		*FRT DOOR ASSY RH	Bent	907.68 FL	*795.30 FL
3	1		*SIDE MIRROR COVER RH	Repair	949.20 FL	*- FL
4	1		*FRT OUTER HANDLE RH	Serviceable	375.57 FL	*- FL
5	1		*REAR DOOR RH	Bent	843.27 FL	*799.50 FL
6	1		*ROCKER PANEL GARNISH	Mtg Cracked	438.17 FL	*438.17 FL
7	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
8	1		*FRT DOOR KEY LOCK COVER	Dented	25.70 FL	*25.70 FL
9	1		*FRT FENDER HYBRID EMBLEM	Necessary	61.70 FL	*61.70 FL
10	1		*REAR WHEEL RIM	Dented	550.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,151.29	2,400.37
- List Item Discount on L Items 20.00/20.00% (\$\$)	720.26	424.07
Total Parts (\$\$)	3,431.03	1,976.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT.STRAIGHTEN CHASSIS MEMBER,REPAIR/RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PART.REFIT INTO POSITION	New	1,000.00	700.00
2	TO SPRAY PAINTING	New	1,000.00	950.00
3	TRANSFER FRT & REAR DOOR MECHANISM	New	300.00	120.00
4	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
Gross Labour Cost (\$)			2,350.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >