

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21009749/T1qce2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	06/10/2021	
	ATTN: LOH CYNTH	AIF	Code	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKK 9271L	Veh. Inspected	SJQ 8116P	
	Policy No.	GA378073/1	Coverage (\$)	0.00	
	Claim No.	S1M03I33	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	17/09/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	MR053HY9305111482	Colour	RED	
	Odometer	110081 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5. General Information					
	Accident Date	16/09/2021	Inspect Date / Time	17/09/2021 (05:39 PM)	
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000-\$16,000				
5b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days			

Report Ref No. CS3/ASM21009749/T1qce2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser