

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG21009751/ATCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant: ORIENTAL SHEET PILING PTE LTD  
Date of Loss: 07/09/2021

Policy No: 2070171472  
Nature of Claim: OD Claim No: 2104156696SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SGZ6633P**  
Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB047111  
Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: WAUZZZF16KD006122  
Colour: Grey Odometer: 42517 km  
Engine Capacity: 2995 cc  
Market Value/New Car Price: S\$280,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/40R22 Rear Tyre Size: 235/40R22  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,395.00	7,779.20	3,615.80	31.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,602.00	1,350.00	34.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,347.00</b>	<b>10,381.20</b>	<b>4,965.80</b>	<b>32.36</b>
<b>- Excess (S\$)</b>	1,400.00	1,400.00	0.00	0.00
<b>(S\$)</b>	13,947.00	8,981.20	4,965.80	35.60
<b>+ GST 7.00/7.00% (S\$)</b>	976.29	628.68	347.61	35.61
<b>Nett Amount (S\$)</b>	<b>14,923.29</b>	<b>9,609.88</b>	<b>5,313.41</b>	<b>35.60</b>

**INSPECTION**

Date of Assignment: 15/09/2021

Date Inspected: 15/09/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,813.00 FS	*3,050.40 FS
2	1		*FRONT BUMPER TRIM CENTER	Deformed	406.00 FS	*324.80 FS
3	1		*FRONT BUMPER TRIM LOWER	Deformed	539.00 FS	*430.80 FS
4	1		*FRONT BUMPER GRILLE LOWER CENTER	Deformed	254.00 FS	*202.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	292.00 FS	*- FS
6	2		*FRONT WHEEL ARC TRIMS LH/RH	Necessary	1,150.00 FS	*920.00 FS
7	1		*RADIATOR GRILLE	Cracked	2,500.00 FS	*2,000.00 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT CENTER	Not Necessary	278.00 FS	*- FS
9	1		*FRONT AIR GUIDE GRILLE RH	Not Necessary	437.00 FS	*- FS
10	1		*FRONT AIR GUIDE GRILLE DECORATIVE FRAME RH	Not Necessary	333.00 FS	*- FS
11	1		*RADIATOR AIR GUIDE LOWER	Not Necessary	42.00 FS	*- FS
12	1		*SUNDRIES	Necessary	300.00 FS	*9.60 FS
13	1		*FRONT BUMPER TRIM - CENTER (Supplementary)	Deformed	244.50 FS	*195.60 FS
14	1		*FRONT BUMPER UNDERRUN BAR (Supplementary)	Deformed	806.50 FS	*645.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	11,395.00	7,779.20
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL FRONT BUMPER WIRE HARNESS FOR HEADLIGHT AND SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	600.00
3	TO RESPRAY FRONT BUMPER,RADIATOR GRILLE TRIM AND BOTH FRONT WHEEL ARC TRIM	New	2,200.00	1,450.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,952.00</b>	<b>2,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >