

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21009753/ARS3Q2**Date:** 18/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100491340
Claimant Vehicle No :	SMF3007B	Insured Vehicle No :	SLH8844U
Date of Loss:	16/09/2021	Nature of Claim:	TP
		Claim No:	5144047062SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3007B		
Make & Model:	AUDI A3, 1.4 TFSI S-TRONIC (A)	Engine No:	CZE802080
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V7J1083226
Colour:	Red	Odometer:	40942 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,361.00	1,555.20	1,805.80	53.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,122.00	2,322.00	1,800.00	43.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,483.00	3,877.20	3,605.80	48.19
+ GST 7.00/7.00% (S\$)	523.81	271.40	252.41	48.19
Nett Amount (S\$)	8,006.81	4,148.60	3,858.21	48.19
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,550.60		

INSPECTION

Date of Assignment:	20/09/2021		
Date Inspected:	20/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	32.00 FS	*- FS
4	1		*REAR SPOILER	Not Necessary	237.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	603.00 FS	*- FS
7	2		*REAR BUMPER BRACKET -LH/RH	Not Necessary	56.00 FS	*- FS
8	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
9	4		*REAR PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	3,361.00 1,555.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR END PANELLING	New	700.00	250.00
2	TO RESPRAY REAR END PANELLING	New	1,000.00	550.00
3	TO REMOVE & REINSTALL REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
4	TO DISMANTLE AND RENEW REAR BUMPER REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
5	TO RESPRAY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RESPRAY REAR BUMPER	New	900.00	550.00
Gross Labour Cost (\$)			4,122.00	2,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >