

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009754/AQC�2**Date:** 29/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00119942103	
Claimant Vehicle No :	SDB3337B	Insured Vehicle No :	SKU2940H	
Date of Loss:	16/09/2021	Nature of Claim:	TP	Claim No: SNM21D205267/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDB3337B		Engine No:	1ZRY091175
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)		Chassis No:	MR053REH104515368
Reg. Date:	04/09/2014 (Man. Year: 2014)		Odometer:	198821 km
Colour:	Brown			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,045.55	5,321.64	4,723.91	47.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,710.00	1,090.00	28.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,845.55	8,031.64	5,813.91	41.99
Approved Total (Overridden) (\$\$)		6,400.00		
Nett Amount (\$\$)	13,845.55	6,400.00	7,445.55	53.78

INSPECTION

Date of Assignment:	22/09/2021	Chin Meng Motors (HQ) 1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit Singapore 417883
Date Inspected:	20/09/2021 Inspected At:	
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDB3337B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	795.60 FL	*795.60 FL
2	1		*BOOTLID EMBLEM-LOGO	Necessary	61.10 FL	*61.10 FL
3	1		*BOOTLID EMBLEM-COROLLA	Necessary	63.90 FL	*63.90 FL
4	1		*BOOTLID EMBLEM-ALTIS	Necessary	51.90 FL	*51.90 FL
5	1		*BOOTLID LAMP	N/s Cracked	743.50 FL	*371.75 FL
6	2		*BOOTLID HINGES	Not Necessary	364.10 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Cut	231.35 FL	*231.35 FL
8	1		*BOOTLID INNER LOCK	Damaged	371.75 FL	*371.75 FL
9	1		*BOOTLID INSULATOR	Not Necessary	261.60 FL	*- FL
10	11		*BOOTLID INSULATOR CLIPS	Not Necessary	38.50 FL	*- FL
11	1		*BOOTLID GARNISH	Not Necessary	299.60 FL	*- FL
12	2		*TAILLAMPS	N/s Cracked/O/s Cut	825.00 FL	*825.00 FL
13	4		*BOOTLID STOPPERS	Not Necessary	50.00 FL	*- FL
14	2		*TAILLAMP CLIP	Necessary	20.00 FL	*20.00 FL
15	2		*TAILLAMP LOWER BRACKET	Cracked	157.00 FL	*110.00 FL
16	1		*REAR BUMPER	Distorted	571.45 FL	*571.45 FL
17	2		*REAR BUMPER RETAINERS	Necessary	181.74 FL	*181.74 FL
18	2		*REAR BUMPER BRACKETS	Bent	362.20 FL	*186.00 FL
19	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Dented	399.80 FL	*399.80 FL
21	2		*REAR BUMPER SENSORS	Damaged	370.60 FL	*370.60 FL
22	2		*REAR BUMPER REFLECTOR	Not Necessary	173.80 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	133.52 FL	*133.52 FL
24	1		*REAR L/H FENDER	Buckled	1,359.60 FL	*987.00 FL
25	1		*REAR FENDER INNER TRIM BOARD	N/s Crumpled	1,183.20 FL	*338.00 FL
26	12		*REAR L/H FENDER INNER TRIM BOARD CLIPS	Necessary	42.00 FL	*21.00 FL
27	1		*REAR L/H FENDER MUDFLAP	Not Necessary	98.50 FL	*- FL
28	1		*REAR L/H FENDER AIR DUCT	Not Necessary	78.50 FL	*- FL
29	1		*REAR L/H FENDER INNER PANEL	Repair	678.90 FL	*- FL
30	1		*FUEL TANK	Not Necessary	971.75 FL	*- FL
31	1		*FUEL TANK NECK	Not Necessary	189.50 FL	*- FL
32	1		*REAR END PANEL	Distorted	381.90 FL	*381.90 FL
33	1		*REAR END PANEL GARNISH	Deformed	371.44 FL	*239.00 FL
34	1		*REAR END PANEL GARNISH INNER COVER	Not Necessary	171.10 FL	*- FL
35	1		*SPARE TYRE PANEL	Repair	896.50 FL	*- FL
36	1		*SPARE TYRE PANEL COVER	Torn	288.50 FL	*288.50 FL
37	1		*REAR WINDSCREEN GUM	Necessary	50.00 FS	*50.00 FS
38	1		*REAR NO PLATE WITH COVER	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,362.40	7,078.86
- List Item Discount on L Items 25.00/25.00% (S\$)	3,316.85	1,757.22
Total Parts (S\$)	10,045.55	5,321.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING,WELDING,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC	New	1,600.00	1,200.00
2	TO RESPRAY AFFECTED PART	New	1,600.00	1,000.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & REFIT REAR INNER TRIMS,SEAT ASSY AND ROOF LINING TO FACILITATE REPAIR	New	150.00	80.00
5	TO REMOVE & REFIT FUEL TANK	New	100.00	80.00
6	TO REMOVE & REFIT REAR REVERSE SENSOR	New	60.00	60.00
7	TOWING CHARGES	New	60.00	60.00
8	TO APPLY UNDERSEAL	New	80.00	80.00
9	TO REMOVE & REFIT OF WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			3,800.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >