### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Pauline Tham Date: 25 Nov 2021

# **Preliminary Advice**

: SKU2940H Insured

Vehicle No

TP Vehicle Accident Date : SDB3337B : 16/09/2021

No

: TOYOTA COROLLA ALTIS Make Assignment Date: 22/09/2021

: 20/09/2021 Date of Est. Duration of

: 9 Inspection Repair

Inspection At: CHIN MENG MOTORS (HQ)

1 KAKI BUKIT AVE 6 #01-40/63, AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 14,027.76 **Revised Amount** :S\$ 8.031.65 Check Items (Estimated) :S\$ 0.00 Total :S\$ 8.031.65

Lump Sum Repair :S\$ 6,400.00

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

(	) The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.