

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009755/NES3Q2
Date: 13/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800046821-02
Claimant Vehicle No :	SH8143B	Insured Vehicle No :	GBH3182Y
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	8902536926SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8143B	Engine No:	G4LEKU408488
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU189806
Reg. Date:	19/12/2019 (Man. Year: 2019)	Odometer:	148531 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	DURATURN 7 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	DURATURN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,649.96	2,986.60	663.36	18.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	850.00	650.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,149.96	3,836.60	1,313.36	25.50
+ GST 7.00/7.00% (S\$)	360.50	268.56	91.94	25.50

Nett Amount (S\$)	5,510.46	4,105.16	1,405.30	25.50
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,632.73		
Global Sum Settlement (S\$)		4,630.00		

INSPECTION

Date of Assignment: 17/09/2021

Date Inspected: 17/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Dented	430.90 FL	*430.90 FL
2	1		*FRONT HEADLAMP RH	Scratched	1,993.65 FL	*1,993.65 FL
3	1		*FRONT BUMPER GRILLE RH	Scratched	186.90 FL	*186.90 FL
4	1		*FRONT DAYLIGHT RH	Serviceable	642.50 FL	*- FL
5	1		*FRONT BUMPER BRACKET RH	Necessary	35.00 FL	*35.00 FL
6	1		*FRONT FENDER RH	Dented	588.80 FL	*588.80 FL
7	1		*FRONT FENDER SHIELD RH	Not Necessary	164.70 FL	*- FL
8	1		*FRT FENDER EMBLEM	Necessary	26.60 FL	*26.60 FL
9	1		*FRONT RH WHEEL COVER	Scratched	346.40 FL	*346.40 FL
10	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
11	1		*FRT FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,537.45	3,708.25
- List Item Discount on L Items 20.00/20.00% (\$)	887.49	721.65
Total Parts (\$)	3,649.96	2,986.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	640.00	350.00
2	SPRAY PAINTING	New	800.00	500.00
3	CHECK LIGHTING	New	60.00	0.00
Gross Labour Cost (\$\$)			1,500.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >