

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009762/EGA3Q2**Date:** 10/05/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2070035082 |
| Claimant Vehicle No : | CB7359Z | Insured Vehicle No : | SJZ7799C |
| Date of Loss: | 16/09/2021 | Nature of Claim: | TP |
| | | Claim No: | 4383471116SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | CB7359Z | Engine No: | ZD30032088 |
| Make & Model: | NISSAN URVAN, 3.0 D (M) | Chassis No: | JN1TG4E25Z0700300 |
| Reg. Date: | 18/02/2004 (Man. Year: 2003) | Odometer: | 525824 km |
| Colour: | White | | |
| Engine Capacity: | 2953 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 185 R15C | Rear Tyre Size: | 185 R15C |
| Front Left Side: | Dunlop 4 mm | Rear Left Side: | Dunlop 4 mm |
| Front Right Side: | Dunlop 4 mm | Rear Right Side: | Dunlop 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 912.00 | 912.00 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 930.00 | 580.00 | 350.00 | 37.63 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 1,842.00 | 1,492.00 | 350.00 | 19.00 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 17/09/2021 | | |
| Date Inspected: | 20/09/2021 | Inspected At: | Connect3 (HQ) 566 Woodlands Road Singapore 728697 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------|-----------|--------------------------|---------------|
| 1 | 1 | | *FRONT BUMPER | Cut | 733.80 F | *733.80 F |
| 2 | 10 | | *FRONT BUMPER CLIPS | Necessary | 30.00 F | *30.00 F |
| 3 | 1 | | *FRONT LH SIDE LAMP | Broken | 148.20 F | *148.20 F |
| | | | | | Total Parts (S\$) | 912.00 |
| | | | | | | 912.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|----------------|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | CHECK WIRING | New | 30.00 | 30.00 |
| 2 | LABOUR CHARGES | New | 600.00 | 250.00 |
| 3 | SPRAY PAINTING | New | 300.00 | 300.00 |
| Gross Labour Cost (\$) | | | 930.00 | 580.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >