

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21009763/BQF3N2**Date:** 13/12/2021REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SMF6887H**Insured Vehicle No :** SGF2353D

Date of Loss: 12/09/2021

Nature of Claim: TP

Claim No: DMPC2100312H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF6887H**

Make & Model: MITSUBISHI EVO-10, 2.0 GSR (M)

Engine No: 4B11BM3663

Reg. Date: 06/06/2008 (Man. Year: 2008)

Chassis No: CZ4A0005664

Colour: White

Odometer: 189272 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35R18

Rear Tyre Size: 265/35R18

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,849.95	2,752.47	5,097.48	64.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	1,600.00	2,270.00	58.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,719.95	4,352.47	7,367.48	62.86
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	11,719.95	3,450.00	8,269.95	70.56
+ GST 7.00/7.00% (S\$)	820.40	241.50	578.90	70.56
Nett Amount (S\$)	12,540.35	3,691.50	8,848.85	70.56

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 20/09/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2021)

Parts: M1-MPV MITSUBISHI EVO-10 2.0 GSR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF6887H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	789.90 FL	*789.90 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	23.50 FL	*23.50 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Necessary	23.50 FL	*23.50 FL
4	1		*RH TAILLAMP ASSY	Not Damaged	488.00 FL	*- FL
5	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	55.40 FL	*55.40 FL
6	1		*REAR RH FENDER	Dented	919.30 FL	*919.30 FL
7	1		*REAR RH FENDER SPLASH SHIELD	Not Damaged	109.10 FL	*- FL
8	1		*REAR RH FENDER INNER TRIM BOARD	Not Damaged	385.00 FL	*- FL
9	1		*REAR RH DOOR	Dented	859.85 FL	*859.85 FL
10	1		*REAR RH DOOR FRAME BLACK TAPE	Necessary	31.30 FL	*31.30 FL
11	1		*RH SIDE ROCKER PANEL GARNISH	Not Damaged	879.10 FL	*- FL
12	1		*REAR RH LOWER ARM	Not Damaged	384.10 FL	*- FL
13	1		*REAR RH SHOCK ABSORBER	Not Damaged	413.10 FL	*- FL
14	1		*REAR RH KNUCKLE ARM	Not Damaged	567.50 FL	*- FL
15	1		*REAR RH WHEEL BEARING	Not Damaged	479.30 FL	*- FL
16	1		*REAR RH UPPER ARM	Not Damaged	192.00 FL	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
19	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
20	1		*REAR RH SPORT RIM (LOCAL REPAIR)	Cut	1,200.00 FS	*200.00 FS
21	1		*REAR RH TYRE	Not Damaged	380.00 FS	*- FS
22	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
23	1		*SET REAR RH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,509.95	3,022.75
- List Item Discount on L Items 10.00/10.00% (\$\$)	660.00	270.28
Total Parts (\$\$)	7,849.95	2,752.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,400.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	600.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	120.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE RH REAR FENDER INNER TRIMS,GARNISH,ROOF LINING,SEATS AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
7	REMOVE AND REPLACE RH REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	0.00
8	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
9	REMOVE AND REINSTALL RH REAR DOOR INNER MECHANISM TO NEW DOOR	New	100.00	80.00
Gross Labour Cost (\$)			3,870.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >