

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21009767/BTF3N2**Date:** 01/10/2021**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MPC21P00182900
Claimant Vehicle No :	SLQ8822K	Insured Vehicle No :	SLN8751Y
Date of Loss:	16/09/2021	Nature of Claim:	TP
		Claim No:	DMPC2100324H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8822K	Engine No:	2ZR8054250
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Chassis No:	ZYX102019672
Reg. Date:	03/08/2017 (Man. Year: 2017)	Odometer:	70809 km
Colour:	Red		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,151.02	2,530.26	3,620.76	58.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,080.00	2,320.00	68.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,551.02	3,610.26	5,940.76	62.20
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	9,551.02	3,600.00	5,951.02	62.31
+ GST 7.00/7.00% (\$\$)	668.57	252.00	416.57	62.31
Nett Amount (\$\$)	10,219.59	3,852.00	6,367.59	62.31

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 20/09/2021 Inspected At:

160 SIN MING DR
 #01-14 SIN MING AUTO CITY
 SINGAPORE 575722
 REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8822K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,124.50 FL	*855.10 FL
2	1		*REAR BUMPER LOWER LID	Broken	465.00 FL	*397.60 FL
3	1		*REAR BUMPER LOWER LID CENTRE GARNISH	Not Damaged	68.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	168.00 FL	*168.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	578.90 FL	*393.20 FL
6	2		*REAR BUMPER INNER S-SIDE BRACKET	No such part	208.40 FL	*- FL
7	1		*REAR BUMPER TOW COVER	Not Damaged	35.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LH	Broken	218.00 FL	*118.00 FL
9	1		*REAR BUMPER REFLECTOR GARNISH LH	Broken	135.00 FL	*135.00 FL
10	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Short Circuit (2 Pcs only)	740.00 FL	*200.00 FL
11	1		*REAR END PANEL	Repair	789.10 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Damaged	285.70 FL	*- FL
13	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	987.90 FL	*- FL
14	1		*REAR FENDER ARCH GARNISH LH	Broken	295.00 FL	*201.35 FL
15	1		*TAILLAMP LH	Broken	982.20 FL	*566.10 FL
16	1		*TAILLAMP LOWER BRACKET LH	Broken	78.00 FL	*78.00 FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*REAR BUMPER LOWER LID CLIPS	Necessary	50.00 FS	*20.00 FS
20	1		*REAR BUMPER REFLECTOR GARNISH CLIPS	No such part	50.00 FS	*- FS
21	1		*REAR BUMPER REVERSE SENSOR SEAL (4 Pcs)	Necessary (2 Pcs only)	192.00 FS	*96.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
25	1		*REAR FENDER ARCH GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,940.70	3,308.35
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,789.68	778.09
Total Parts (\$\$)	6,151.02	2,530.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
2	CHECK WIRING	New	100.00	20.00
3	UPHOLSTERY	New	300.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
5	PANEL BEATING	New	1,200.00	600.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (\$\$)			3,400.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >