

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 4956E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR ASSEMBLY LH (BENT)	NOT CONSISTENT WITH THE IMPACT	1,765.00	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	210.00	-
1	SIDE MIRROR ASSY	GRAZED / DEFORMED	750.00	750.00
	LESS 25% DISCOUNT		-681.25	-187.50
			2,043.75	562.50
	<u>LABOUR</u>			
	TO CHECK AND RECONNECT SNAP WIRING.		150.00	30.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	180.00	-
	TO REMOVE AND TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	150.00	-
	TO RESPRAY AFFECTED AREAS.	NOT NECESSARY	1,200.00	-
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR DOOR CENTER PILLAR (INNER), FRONT DOOR PILLAR, AND ALIGNED ALL PARTS.	NOT NECESSARY	1,400.00	-
	TO REMOVE AND REPLACE SIDE MIRROR ASSY.		180.00	80.00
			3,260.00	110.00
	GRAND TOTAL		5,303.75	672.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CS3/ASM21004737/Eqce2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.